





























































	ЗК-1	(100054)	ЗК-6
	$F \text{ см}^2 = 7.06$ $Q \text{ кг} = 1.91$ $D \text{ оп.мм} = 140.2$ $P \text{ н.мм} = 373.8$ $P \text{ в.мм} = 103.2$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$		$F \text{ см}^2 = 4.921$ $Q \text{ кг} = 1.334$ $D \text{ оп.мм} = 75.1$ $P \text{ н.мм} = 302.9$ $P \text{ в.мм} = 178.9$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	ЗК-2	(ЯВ-2)	ЗК-7
	$F \text{ см}^2 = 6.021$ $Q \text{ кг} = 1.632$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 342.1$ $P \text{ в.мм} = 142.5$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = П$		$F \text{ см}^2 = 0.901$ $Q \text{ кг} = 0.244$ $D \text{ оп.мм} = 15$ $P \text{ н.мм} = 47.1$ $P \text{ в.мм} = 33$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$
	ЗК-3	(РОСТ-10)	ЗК-8
	$F \text{ см}^2 = 4.52$ $Q \text{ кг} = 1.225$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 287$ $P \text{ в.мм} = 107.3$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = П$		$F \text{ см}^2 = 1.76$ $Q \text{ кг} = 0.477$ $D \text{ оп.мм} = 37$ $P \text{ н.мм} = 126$ $P \text{ в.мм} = 36$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	ЗК-4	(РДГ-79)	ЗК-9
	$F \text{ см}^2 = 7.23$ $Q \text{ кг} = 1.96$ $D \text{ оп.мм} = 126.3$ $P \text{ н.мм} = 309.2$ $P \text{ в.мм} = 26.4$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 6.402$ $Q \text{ кг} = 1.735$ $D \text{ оп.мм} = 106$ $P \text{ н.мм} = 312$ $P \text{ в.мм} =$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$
(100005)	ЗК-5	(В75.10)	ЗК-10
	$F \text{ см}^2 = 13.28$ $Q \text{ кг} = 3.6$ $D \text{ оп.мм} = 184.2$ $P \text{ н.мм} = 624.6$ $P \text{ в.мм} = 379.9$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 20.42$ $Q \text{ кг} = 5.534$ $D \text{ оп.мм} = 75$ $P \text{ н.мм} = 235.6$ $P \text{ в.мм} = 172.8$ $\Gamma \text{р. сл.} = I$ $\text{Точн.} = Н$











(Б-59)	ЗК-11	(100009)	ЗК-16
	$F \text{ см}^2 = 4.129$ $Q \text{ кг} = 1.119$ $D \text{ оп.мм} = 62$ $P \text{ н.мм} = 196.1$ $P \text{ в.мм} = 164.2$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 7.31$ $Q \text{ кг} = 1.981$ $D \text{ оп.мм} = 109.7$ $P \text{ н.мм} = 377.4$ $P \text{ в.мм} = 253.5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \Pi$
(ПР-40)	ЗК-12		ЗК-17
	$F \text{ см}^2 = 3.75$ $Q \text{ кг} = 1.016$ $D \text{ оп.мм} = 43.4$ $P \text{ н.мм} = 309.4$ $P \text{ в.мм} = 62.8$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 1.618$ $Q \text{ кг} = 0.439$ $D \text{ оп.мм} = 41.4$ $P \text{ н.мм} = 164.7$ $P \text{ в.мм} =$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = \Pi$
(ПР-60)	ЗК-13		ЗК-18
	$F \text{ см}^2 = 3.03$ $Q \text{ кг} = 0.821$ $D \text{ оп.мм} = 63$ $P \text{ н.мм} = 209.7$ $P \text{ в.мм} = 94$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 1.84$ $Q \text{ кг} = 0.499$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100$ $P \text{ в.мм} = 84$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$
(Т-1)	ЗК-14		ЗК-19
	$F \text{ см}^2 = 1.347$ $Q \text{ кг} = 0.365$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 96.3$ $P \text{ в.мм} = 83.1$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 3.513$ $Q \text{ кг} = 0.952$ $D \text{ оп.мм} = 76$ $P \text{ н.мм} = 244$ $P \text{ в.мм} = 62.9$ $\Gamma \text{р. сл.} = VII$ $\text{Точн.} = \Pi$
(Т-18)	ЗК-15		ЗК-20
	$F \text{ см}^2 = 0.864$ $Q \text{ кг} = 0.234$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 72.3$ $P \text{ в.мм} = 60.7$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$		$F \text{ см}^2 = 2.464$ $Q \text{ кг} = 0.668$ $D \text{ оп.мм} = 34.5$ $P \text{ н.мм} = 134.2$ $P \text{ в.мм} = 63.7$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = \Pi$











	3К-21	(С9)	3К-26
	$F \text{ см}^2 = 2,64$ $Q \text{ кг} = 0,715$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78,5$ $P \text{ в.мм} = 53,4$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 11,94$ $Q \text{ кг} = 3,236$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 160,3$ $P \text{ в.мм} = 99$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
(С5)	3К-22	(С10)	3К-27
	$F \text{ см}^2 = 14,61$ $Q \text{ кг} = 3,959$ $D \text{ оп.мм} = 54$ $P \text{ н.мм} = 165,5$ $P \text{ в.мм} = 88$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 21,55$ $Q \text{ кг} = 5,84$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 201$ $P \text{ в.мм} = 110$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
(С6)	3К-23	(С11)	3К-28
	$F \text{ см}^2 = 17,04$ $Q \text{ кг} = 4,618$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 179,4$ $P \text{ в.мм} = 99$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 14,896$ $Q \text{ кг} = 4,037$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 160,3$ $P \text{ в.мм} = 99$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
(С7)	3К-24		3К-29
	$F \text{ см}^2 = 9,89$ $Q \text{ кг} = 2,68$ $D \text{ оп.мм} = 80$ $P \text{ н.мм} = 251,3$ $P \text{ в.мм} = 225,3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4,43$ $Q \text{ кг} = 1,201$ $D \text{ оп.мм} = 43,3$ $P \text{ н.мм} = 342$ $P \text{ в.мм} = 83,9$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
(С8)	3К-25		3К-30
	$F \text{ см}^2 = 18,22$ $Q \text{ кг} = 4,939$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 179,4$ $P \text{ в.мм} = 91,1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 85,23$ $Q, \text{ кг} = 23,1$ $D \text{ оп.мм} = 167,6$ $P \text{ н.мм} = 496,4$ $P \text{ в.мм} = 320,7$ $\Gamma \text{р. сл.} = \text{Особ.}$ $\text{Точн.} = \text{П}$











	3К-31		3К-36
	$F, \text{ см}^2 = 2,462$ $Q, \text{ кг} = 0,667$ $D_{\text{оп.мм}} = 47,1$ $P_{\text{н.мм}} = 171,5$ $P_{\text{в.мм}} = 44,3$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 2,52$ $Q \text{ кг} = 0,683$ $D_{\text{оп.мм}} = 52,3$ $P_{\text{н.мм}} = 226,4$ $P_{\text{в.мм}} = 65,5$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \Pi$
	3К-32		3К-37
	$F, \text{ см}^2 = 1,592$ $Q, \text{ кг} = 0,43$ $D_{\text{оп.мм}} = 40$ $P_{\text{н.мм}} = 110,9$ $P_{\text{в.мм}} = 101,4$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 7,67$ $Q \text{ кг} = 2,08$ $D_{\text{оп.мм}} = 129,7$ $P_{\text{н.мм}} = 388$ $P_{\text{в.мм}} = 212$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \text{H}$
	3К-33		3К-38
	$F, \text{ см}^2 = 8,7$ $Q, \text{ кг} = 2,358$ $D_{\text{оп.мм}} = 55$ $P_{\text{н.мм}} = 315$ $P_{\text{в.мм}} = 22$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 6,1585$ $Q \text{ кг} = 1,668$ $D_{\text{оп.мм}} = 83,5$ $P_{\text{н.мм}} = 349,6$ $P_{\text{в.мм}} = 167,7$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \Pi$
	3К-34		3К-39
	$F \text{ см}^2 = 4,79$ $Q \text{ кг} = 1,3$ $D_{\text{оп.мм}} = 43,3$ $P_{\text{н.мм}} = 339$ $P_{\text{в.мм}} = 65,4$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 2,285$ $Q \text{ кг} = 0,617$ $D_{\text{оп.мм}} = 26,7$ $P_{\text{н.мм}} = 108,4$ $P_{\text{в.мм}} = 26,4$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \text{H}$
	3К-35		3К-40
	$F \text{ см}^2 = 3,03$ $Q \text{ кг} = 0,821$ $D_{\text{оп.мм}} = 52,5$ $P_{\text{н.мм}} = 240$ $P_{\text{в.мм}} = 65,1$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 3,076$ $Q \text{ кг} = 0,834$ $D_{\text{оп.мм}} = 70$ $P_{\text{н.мм}} = 161,8$ $P_{\text{в.мм}} = 145,8$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$

	3К-41		3К-46
	<p> $F \text{ см}^2 = 14,45$ $Q \text{ кг} = 3,916$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 202$ $P \text{ в.мм} = 147,7$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p> $F \text{ см}^2 = 5,944$ $Q \text{ кг} = 1,61$ $D \text{ оп.мм} = 51,9$ $P \text{ н.мм} = 331,7$ $P \text{ в.мм} = 140$ $\Gamma \text{ р. сл.} = \text{VII}$ $\text{Точн.} = \text{H}$ </p>
	3К-42		3К-47
	<p> $F \text{ см}^2 = 4,7$ $Q \text{ кг} = 1,274$ $D \text{ оп.мм} = 86$ $P \text{ н.мм} = 272$ $P \text{ в.мм} = 198$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>		<p> $F \text{ см}^2 = 4,89$ $Q \text{ кг} = 1,325$ $D \text{ оп.мм} = 67,5$ $P \text{ н.мм} = 285,7$ $P \text{ в.мм} = 85,6$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$ </p>
	3К-43		3К-48
	<p> $F \text{ см}^2 = 14,74$ $Q \text{ кг} = 3,995$ $D \text{ оп.мм} = 203,3$ $P \text{ н.мм} = 795$ $P \text{ в.мм} = 202,6$ $\Gamma \text{ р. сл.} = \text{VII}$ $\text{Точн.} = \text{ОСОВЯ}$ </p>		<p> $F \text{ см}^2 = 7,24$ $Q \text{ кг} = 1,962$ $D \text{ оп.мм} = 117$ $P \text{ н.мм} = 351,8$ $P \text{ в.мм} = 178$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$ </p>
	3К-44		3К-49
	<p> $F \text{ см}^2 = 11,65$ $Q \text{ кг} = 3,157$ $D \text{ оп.мм} = 147,3$ $P \text{ н.мм} = 615,5$ $P \text{ в.мм} = 202,6$ $\Gamma \text{ р. сл.} = \text{VII}$ $\text{Точн.} = \text{ОВОВЯ}$ </p>		<p> $F \text{ см}^2 = 34,88$ $Q \text{ кг} = 9,452$ $D \text{ оп.мм} = 206$ $P \text{ н.мм} = 809,8$ $P \text{ в.мм} = 384$ $\Gamma \text{ р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$ </p>
	3К-45		3К-50
	<p> $F \text{ см}^2 = 3,253$ $Q \text{ кг} = 0,881$ $D \text{ оп.мм} = 57$ $P \text{ н.мм} = 170$ $P \text{ в.мм} = 156$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{H}$ </p>		<p> $F \text{ см}^2 = 30,1$ $Q \text{ кг} = 8,157$ $D \text{ оп.мм} = 150$ $P \text{ н.мм} = 1024$ $P \text{ в.мм} = 320,6$ $\Gamma \text{ р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$ </p>











	<p>3K-51</p> <p> $F \text{ см}^2 = 7.277$ $Q \text{ кг} = 1.972$ $D \text{ оп.мм} = 86.5$ $P \text{ н.мм} = 296.9$ $P \text{ в.мм} = 156.6$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{H}$ </p>		<p>3K-56</p> <p> $F \text{ см}^2 = 5.7$ $Q \text{ кг} = 1.55$ $D \text{ оп.мм} = 108.5$ $P \text{ н.мм} = 481.5$ $P \text{ в.мм} =$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>3K-52</p> <p> $F \text{ см}^2 = 4.58$ $Q \text{ кг} = 1.237$ $D \text{ оп.мм} = 16.5$ $P \text{ н.мм} = 91$ $P \text{ в.мм} = 38.17$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>		<p>3K-57</p> <p> $F \text{ см}^2 = 2.758$ $Q \text{ кг} = 0.745$ $D \text{ оп.мм} = 29.7$ $P \text{ н.мм} = 198.1$ $P \text{ в.мм} = 28$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>
	<p>3K-53</p> <p> $F \text{ см}^2 = 3.052$ $Q \text{ кг} = 0.827$ $D \text{ оп.мм} = 84.84$ $P \text{ н.мм} = 240$ $P \text{ в.мм} = 230.4$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$ </p>		<p>3K-58</p> <p> $F \text{ см}^2 = 12.052$ $Q \text{ кг} = 3.266$ $D \text{ оп.мм} = 126.5$ $P \text{ н.мм} = 536.2$ $P \text{ в.мм} = 614$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$ </p>
	<p>3K-54</p> <p> $F \text{ см}^2 = 6.97$ $Q \text{ кг} = 1.89$ $D \text{ оп.мм} = 177$ $P \text{ н.мм} = 555$ $P \text{ в.мм} = 132$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{А}$ </p>		<p>3K-59</p> <p> $F \text{ см}^2 = 5.31$ $Q \text{ кг} = 1.439$ $D \text{ оп.мм} = 56.57$ $P \text{ н.мм} = 281.6$ $P \text{ в.мм} = 233.3$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$ </p>
	<p>3K-55</p> <p> $F \text{ см}^2 = 4.24$ $Q \text{ кг} = 1.15$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 354.4$ $P \text{ в.мм} = 66$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$ </p>		<p>3K-60</p> <p> $F \text{ см}^2 = 19.4$ $Q \text{ кг} = 5.257$ $D \text{ оп.мм} = 110.4$ $P \text{ н.мм} = 292$ $P \text{ в.мм} = 276.1$ $\Gamma \text{р. сл.} = \text{осб.}$ $\text{Точн.} = \text{П}$ </p>






	3К-61		3К-66
	<p> $F \text{ см}^2 = 4,73$ $Q \text{ кг} = 1,282$ $D_{\text{оп.мм}} = 55,8$ $P_{\text{н.мм}} = 147$ $P_{\text{в.мм}} = 140$ $\Gamma_{\text{р. сл.}} = \text{ОСБ}$ $\text{Точн.} = \Pi$ </p>		<p> $F \text{ см}^2 = 3,672$ $Q \text{ кг} = 0,995$ $D_{\text{оп.мм}} = 85,14$ $P_{\text{н.мм}} = 244$ $P_{\text{в.мм}} = 146$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = H$ </p>
	3К-62		3К-67
	<p> $F \text{ см}^2 = 9,432$ $Q \text{ кг} = 2,556$ $D_{\text{оп.мм}} = 80,5$ $P_{\text{н.мм}} = 213$ $P_{\text{в.мм}} = 208$ $\Gamma_{\text{р. сл.}} = \text{ОСБ}$ $\text{Точн.} = \Pi$ </p>		<p> $F, \text{ см}^2 = 11,019$ $Q, \text{ кг} = 2,986$ $D_{\text{оп.мм}} = 80$ $P_{\text{н.мм}} = 552,7$ $P_{\text{вн.мм}} = 478,2$ $\Gamma_{\text{р. сл.}} = VII$ $\text{Точн.} = H$ </p>
	3К-63		3К-68
	<p> $F \text{ см}^2 = 3,205$ $Q \text{ кг} = 0,869$ $D_{\text{оп.мм}} = 28,62$ $P_{\text{н.мм}} = 91$ $P_{\text{в.мм}} = 72$ $\Gamma_{\text{р. сл.}} = B$ $\text{Точн.} = H$ </p>		<p> $F, \text{ см}^2 = 2,323$ $Q, \text{ кг} = 0,629$ $D_{\text{оп.мм}} = 30$ $P_{\text{н.мм}} = 81,91$ $P_{\text{вн.мм}} = 19,16$ $\Gamma_{\text{р. сл.}} = III$ $\text{Точн.} = \Pi$ </p>
	3К-64		3К-69
	<p> $F \text{ см}^2 = 21,206$ $Q \text{ кг} = 5,749$ $D_{\text{оп.мм}} = 140$ $P_{\text{н.мм}} = 440$ $P_{\text{в.мм}} = 408$ $\Gamma_{\text{р. сл.}} = C$ $\text{Точн.} = H$ </p>		<p> $F, \text{ см}^2 = 2,233$ $Q, \text{ кг} = 0,605$ $D_{\text{оп.мм}} = 33,48$ $P_{\text{н.мм}} = 98,15$ $P_{\text{вн.мм}} = 19,16$ $\Gamma_{\text{р. сл.}} = III$ $\text{Точн.} = \Pi$ </p>
	3К-65		3К-70
	<p> $F \text{ см}^2 = 8,77$ $Q \text{ кг} = 2,377$ $D_{\text{оп.мм}} = 207$ $P_{\text{н.мм}} = 457$ $P_{\text{в.мм}} = 1720$ $\Gamma_{\text{р. сл.}} = VI$ $\text{Точн.} = H$ </p>		<p> $F, \text{ см}^2 = 7,058$ $Q, \text{ кг} = 1,913$ $D_{\text{оп.мм}} = 126,3$ $P_{\text{н.мм}} = 340,1$ $P_{\text{вн.мм}} = 26,4$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = \Pi$ </p>







	<p>3K-71</p> <p>$F, \text{см}^2 = 6.103$ $Q, \text{кг} = 1.654$ $D_{\text{оп,мм}} = 53.5$ $P_{\text{н,мм}} = 264.5$ $P_{\text{вн,мм}} = 60.8$ $\Gamma \text{р. сл.} = \text{ОС.}$ $\text{Точн.} = \text{Н}$</p>		<p>3K-76</p> <p>$F, \text{см}^2 = 4.139$ $Q, \text{кг} = 1.122$ $D_{\text{оп,мм}} = 96$ $P_{\text{н,мм}} = 226.9$ $P_{\text{вн,мм}} = 71.7$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$</p>
	<p>3K-72</p> <p>$F, \text{см}^2 = 5.05$ $Q, \text{кг} = 1.369$ $D_{\text{оп,мм}} = 97.83$ $P_{\text{н,мм}} = 344$ $P_{\text{вн,мм}} = 176$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$</p>		<p>3K-77</p> <p>$F, \text{см}^2 = 6.506$ $Q, \text{кг} = 1.763$ $D_{\text{оп,мм}} = 56.4$ $P_{\text{н,мм}} = 301.4$ $P_{\text{вн,мм}} = 95.7$ $\Gamma \text{р. сл.} = \text{ОС.}$ $\text{Точн.} = \text{Н}$</p>
	<p>3K-73</p> <p>$F, \text{см}^2 = 2.711$ $Q, \text{кг} = 0.735$ $D_{\text{оп,мм}} = 47.1$ $P_{\text{н,мм}} = 175.7$ $P_{\text{вн,мм}} = 31.34$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$</p>		<p>3K-78</p> <p>$F, \text{см}^2 = 15.592$ $Q, \text{кг} = 4.225$ $D_{\text{оп,мм}} = 96.4$ $P_{\text{н,мм}} = 326.6$ $P_{\text{вн,мм}} = 339$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$</p>
	<p>3K-74</p> <p>$F, \text{см}^2 = 8.395$ $Q, \text{кг} = 2.275$ $D_{\text{оп,мм}} = 131$ $P_{\text{н,мм}} = 424$ $P_{\text{вн,мм}} = 451$ $\Gamma \text{р. сл.} = \text{ОСОВ.}$ $\text{Точн.} = \text{П}$</p>		<p>3K-79</p> <p>$F, \text{см}^2 = 19.573$ $Q, \text{кг} = 5.304$ $D_{\text{оп,мм}} = 113.14$ $P_{\text{н,мм}} = 530$ $P_{\text{вн,мм}} = 397$ $\Gamma \text{р. сл.} = \text{ОС}$ $\text{Точн.} = \text{Н}$</p>
	<p>3K-75</p> <p>$F, \text{см}^2 = 12.978$ $Q, \text{кг} = 3.519$ $D_{\text{оп,мм}} = 103.11$ $P_{\text{н,мм}} = 423.5$ $P_{\text{вн,мм}} = 91.6$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$</p>		<p>3K-80</p> <p>$F, \text{см}^2 = 5.107$ $Q, \text{кг} = 1.384$ $D_{\text{оп,мм}} = 59.8$ $P_{\text{н,мм}} = 207.9$ $P_{\text{вн,мм}} = 169.2$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$</p>

	3К-81		3К-86
	$F, \text{см}^2 = 1564$ $Q, \text{кг} = 0.424$ $D_{\text{оп.,мм}} = 42.3$ $P_{\text{н.,мм}} = 109$ $P_{\text{вн.,мм}} = 99.6$ $\Gamma_{\text{р. сл.}} = IV$ $\text{Точн.} = Н$		$F, \text{см}^2 = 3.394$ $Q, \text{кг} = 0.92$ $D_{\text{оп.,мм}} = 50$ $P_{\text{н.,мм}} = 176.85$ $P_{\text{вн.,мм}} = 49.4$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = Н$
	3К-82		3К-87
	$F, \text{см}^2 = 6.122$ $Q, \text{кг} = 1.66$ $D_{\text{оп.,мм}} = 65$ $P_{\text{н.,мм}} = 171.9$ $P_{\text{вн.,мм}} = 104.6$ $\Gamma_{\text{р. сл.}} = IV$ $\text{Точн.} = Н$		$F, \text{см}^2 = 10.832$ $Q, \text{кг} = 2.935$ $D_{\text{оп.,мм}} = 80$ $P_{\text{н.,мм}} = 538.2$ $P_{\text{вн.,мм}} = 478.2$ $\Gamma_{\text{р. сл.}} = VII$ $\text{Точн.} = Н$
	3К-83		3К-88
	$F, \text{см}^2 = 4.704$ $Q, \text{кг} = 1.275$ $D_{\text{оп.,мм}} = 79$ $P_{\text{н.,мм}} = 236$ $P_{\text{вн.,мм}} = 77.4$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = Н$		$F, \text{см}^2 = 19.524$ $Q, \text{кг} = 5.291$ $D_{\text{оп.,мм}} = 113.14$ $P_{\text{н.,мм}} = 519.9$ $P_{\text{вн.,мм}} = 397$ $\Gamma_{\text{р. сл.}} = OC.$ $\text{Точн.} = Н$
	3К-84		3К-89
	$F, \text{см}^2 = 17.598$ $Q, \text{кг} = 4.769$ $D_{\text{оп.,мм}} = 150$ $P_{\text{н.,мм}} = 754$ $P_{\text{вн.,мм}} = 258$ $\Gamma_{\text{р. сл.}} = VI$ $\text{Точн.} = Н$		$F, \text{см}^2 = 1.119$ $Q, \text{кг} = 0.303$ $D_{\text{оп.,мм}} = 30$ $P_{\text{н.,мм}} = 79.3$ $P_{\text{вн.,мм}} = 69.9$ $\Gamma_{\text{р. сл.}} = IV$ $\text{Точн.} = Н$
	3К-85		3К-90
	$F, \text{см}^2 = 8.1$ $Q, \text{кг} = 2.195$ $D_{\text{оп.,мм}} = 90.5$ $P_{\text{н.,мм}} = 317.7$ $P_{\text{вн.,мм}} = 122.4$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = Н$		$F, \text{см}^2 = 1.442$ $Q, \text{кг} = 0.319$ $D_{\text{оп.,мм}} = 43.5$ $P_{\text{н.,мм}} = 100.8$ $P_{\text{вн.,мм}} = 91.4$ $\Gamma_{\text{р. сл.}} = IV$ $\text{Точн.} = Н$

	3К-91		3К-96
	$F, \text{ см}^2 = 5.159$ $Q, \text{ кг} = 1.398$ $D_{\text{оп.,мм}} = 80.3$ $P_{\text{н.,мм}} = 274.2$ $P_{\text{вн.,мм}} = 262.2$ $\Gamma_{\text{р. сл.}} = 0 \text{ соб.}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 2.191$ $Q, \text{ кг} = 0.594$ $D_{\text{оп.,мм}} = 20$ $P_{\text{н.,мм}} = 62.8$ $P_{\text{вн.,мм}} = 34.6$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	3К-92		3К-97
	$F, \text{ см}^2 = 7.775$ $Q, \text{ кг} = 2.107$ $D_{\text{оп.,мм}} = 83.4$ $P_{\text{н.,мм}} = 476.1$ $P_{\text{вн.,мм}} = 112.4$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 4.019$ $Q, \text{ кг} = 1.089$ $D_{\text{оп.,мм}} = 28$ $P_{\text{н.,мм}} = 88.0$ $P_{\text{вн.,мм}} = 51.8$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	3К-93		3К-98
	$F, \text{ см}^2 = 4.009$ $Q, \text{ кг} = 1.086$ $D_{\text{оп.,мм}} = 58$ $P_{\text{н.,мм}} = 258.4$ $P_{\text{вн.,мм}} = 136.8$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \square \text{ с.}$		$F, \text{ см}^2 = 5.466$ $Q, \text{ кг} = 1.481$ $D_{\text{оп.,мм}} = 35$ $P_{\text{н.,мм}} = 110$ $P_{\text{вн.,мм}} = 72.1$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	3К-94		3К-99
	$F, \text{ см}^2 = 2.095$ $Q, \text{ кг} = 0.568$ $D_{\text{оп.,мм}} = 38.9$ $P_{\text{н.,мм}} = 95.8$ $P_{\text{вн.,мм}} = 25.1$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп.,мм}} = -$ $P_{\text{н.,мм}} = -$ $P_{\text{вн.,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	3К-95		3К-100
	$F, \text{ см}^2 = 3.958$ $Q, \text{ кг} = 1.073$ $D_{\text{оп.,мм}} = 45$ $P_{\text{н.,мм}} = 141.4$ $P_{\text{вн.,мм}} = 122.5$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп.,мм}} = -$ $P_{\text{н.,мм}} = -$ $P_{\text{вн.,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$

	<p>3K-101</p> <p>$F, \text{см}^2 = 9.524$ $Q, \text{кг} = 2.581$ $D_{\text{оп,мм}} = 146.4$ $P_{\text{н,мм}} = 552.9$ $P_{\text{вн,мм}} = 302.6$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$</p>		<p>3K-106</p> <p>$F, \text{см}^2 = 14.65$ $Q, \text{кг} = 3.97$ $D_{\text{оп,мм}} = 27.3$ $P_{\text{н,мм}} = 338.2$ $P_{\text{вн,мм}} = 229.5$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$</p>
	<p>3K-102</p> <p>$F, \text{см}^2 = 8.56$ $Q, \text{кг} = 2.32$ $D_{\text{оп,мм}} = 123.2$ $P_{\text{н,мм}} = 504.7$ $P_{\text{вн,мм}} = 254.4$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$</p>		<p>3K-107</p> <p>$F, \text{см}^2 = 6.479$ $Q, \text{кг} = 1.756$ $D_{\text{оп,мм}} = 115.76$ $P_{\text{н,мм}} = 337.4$ $P_{\text{вн,мм}} = 300$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$</p>
	<p>3K-103</p> <p>$F, \text{см}^2 = 7.596$ $Q, \text{кг} = 2.059$ $D_{\text{оп,мм}} = 100.5$ $P_{\text{н,мм}} = 456.5$ $P_{\text{вн,мм}} = 206.2$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$</p>		<p>3K-108</p> <p>$F, \text{см}^2 = 19.094$ $Q, \text{кг} = 5.175$ $D_{\text{оп,мм}} = 109$ $P_{\text{н,мм}} = 375.1$ $P_{\text{вн,мм}} = 456.9$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \Pi$</p>
	<p>3K-104</p> <p>$F, \text{см}^2 = 5.33$ $Q, \text{кг} = 1.444$ $D_{\text{оп,мм}} = 98.7$ $P_{\text{н,мм}} = 365.5$ $P_{\text{вн,мм}} = 238.4$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$</p>		<p>3K-109</p> <p>$F, \text{см}^2 = 17.98$ $Q, \text{кг} = 4.873$ $D_{\text{оп,мм}} = 36.1$ $P_{\text{н,мм}} = 257.5$ $P_{\text{вн,мм}} = 197.3$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$</p>
	<p>3K-105</p> <p>$F, \text{см}^2 = 4.31$ $Q, \text{кг} = 1.168$ $D_{\text{оп,мм}} = 72.1$ $P_{\text{н,мм}} = 305.5$ $P_{\text{вн,мм}} = 178.4$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$</p>		<p>3K-110</p> <p>$F, \text{см}^2 = 17.78$ $Q, \text{кг} = 4.82$ $D_{\text{оп,мм}} = 80.85$ $P_{\text{н,мм}} = 238$ $P_{\text{вн,мм}} = 157.1$ $\Gamma_{\text{р. сл.}} = \text{I} \vee$ $\text{Точн.} = \text{H}$</p>

	ЗК-111		ЗК-116
	$F, \text{ см}^2 = 8.246$ $Q, \text{ кг} = 2.235$ $D_{\text{оп, мм}} = 103.6$ $P_{\text{н, мм}} = 344$ $P_{\text{вн, мм}} = 148.7$ $\Gamma_{\text{р. сл.}} = IV$ $\text{Точн.} = Н$		$F, \text{ см}^2 = 4.00$ $Q, \text{ кг} = 1.083$ $D_{\text{оп, мм}} = 54.3$ $P_{\text{н, мм}} = 243.2$ $P_{\text{вн, мм}} = 69.1$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = Н$
	ЗК-112		ЗК-117
	$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп, мм}} = -$ $P_{\text{н, мм}} = -$ $P_{\text{вн, мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп, мм}} = -$ $P_{\text{н, мм}} = -$ $P_{\text{вн, мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	ЗК-113		ЗК-118
	$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп, мм}} = -$ $P_{\text{н, мм}} = -$ $P_{\text{вн, мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп, мм}} = -$ $P_{\text{н, мм}} = -$ $P_{\text{вн, мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	ЗК-114		ЗК-119
	$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп, мм}} = -$ $P_{\text{н, мм}} = -$ $P_{\text{вн, мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$		$F, \text{ см}^2 = 3.135$ $Q, \text{ кг} = 0.85$ $D_{\text{оп, мм}} = 43$ $P_{\text{н, мм}} = 109.6$ $P_{\text{вн, мм}} = 105.7$ $\Gamma_{\text{р. сл.}} = ОС.$ $\text{Точн.} = П$
	ЗК-115		ЗК-120
	$F, \text{ см}^2 = 1.541$ $Q, \text{ кг} = 0.418$ $D_{\text{оп, мм}} = 42.5$ $P_{\text{н, мм}} = 115.3$ $P_{\text{вн, мм}} = 50.3$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = Н$		$F, \text{ см}^2 = 4.843$ $Q, \text{ кг} = 1.312$ $D_{\text{оп, мм}} = 51$ $P_{\text{н, мм}} = 235.2$ $P_{\text{вн, мм}} = 71.5$ $\Gamma_{\text{р. сл.}} = VI$ $\text{Точн.} = Н$

	3К-121		3К-126
	$F, \text{ см}^2 = 8,727$ $Q, \text{ кг} = 2,356$ $D_{\text{оп,мм}} = 67,07$ $P_{\text{н,мм}} = 176,3$ $P_{\text{вн,мм}} = 170,2$ Гр. сл. = ОСБ Точн. = П		$F, \text{ см}^2 = 4,00$ $Q, \text{ кг} = 1,083$ $D_{\text{оп,мм}} = 54,3$ $P_{\text{н,мм}} = 243,2$ $P_{\text{вн,мм}} = 69,1$ Гр. сл. = V Точн. = Н
	3К-122		3К-127
	$F, \text{ см}^2 = 5,313$ $Q, \text{ кг} = 1,440$ $D_{\text{оп,мм}} = 48,3$ $P_{\text{н,мм}} = 151,7$ $P_{\text{вн,мм}} = 127,9$ Гр. сл. = II Точн. = П		$F, \text{ см}^2 = 9,502$ $Q, \text{ кг} = 2,575$ $D_{\text{оп,мм}} = 82$ $P_{\text{н,мм}} = 615$ $P_{\text{вн,мм}} = 188$ Гр. сл. = □С Точн. = Н
	3К-123		3К-128
	$F, \text{ см}^2 = 2,624$ $Q, \text{ кг} = 0,711$ $D_{\text{оп,мм}} = 47,1$ $P_{\text{н,мм}} = 176,7$ $P_{\text{вн,мм}} = 33,2$ Гр. сл. = V I Точн. = П		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп,мм}} = -$ $P_{\text{н,мм}} = -$ $P_{\text{вн,мм}} = -$ Гр. сл. = — Точн. = —
	3К-124		3К-129
	$F, \text{ см}^2 = 97,568$ $Q, \text{ кг} = 26,441$ $D_{\text{оп,мм}} = 175,7$ $P_{\text{н,мм}} = 536,5$ $P_{\text{вн,мм}} = 366,2$ Гр. сл. = ОСБ Точн. = Н		$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп,мм}} =$ $P_{\text{н,мм}} =$ $P_{\text{вн,мм}} =$ Гр. сл. = ОС. Точн. = П
	3К-125		3К-130
	$F, \text{ см}^2 = 13,523$ $Q, \text{ кг} = 3,665$ $D_{\text{оп,мм}} = 94,3$ $P_{\text{н,мм}} = 245,1$ $P_{\text{вн,мм}} = 251$ Гр. сл. = ОСБ Точн. = П		$F, \text{ см}^2 = 4,843$ $Q, \text{ кг} = 1,312$ $D_{\text{оп,мм}} = 51$ $P_{\text{н,мм}} = 235,2$ $P_{\text{вн,мм}} = 71,5$ Гр. сл. = V I Точн. = Н