





























































	ОН-1	(ЭЛ-02)	ОН-6
	$F_{\text{см}^2} = 2.56$ $Q_{\text{кз}} = 0.694$ $D_{\text{оп.мм}} = 82$ $P_{\text{н.мм}} = 260$ Гр. сл. = V1 Точн. = Н		$F_{\text{см}^2} = 6.855$ $Q_{\text{кз}} = 1.858$ $D_{\text{оп.мм}} = 83$ $P_{\text{н.мм}} = 236$ Гр. сл. = I Точн. = П
(ЛA2100)	ОН-2	(ЭЛ-03)	ОН-7
	$F_{\text{см}^2} = 2,385$ $Q_{\text{кз}} = 0.646$ $D_{\text{оп.мм}} = 101$ $P_{\text{н.мм}} = 320.3$ Гр. сл. = VI Точн. = П		$F_{\text{см}^2} = 5.64$ $Q_{\text{кз}} = 1.528$ $D_{\text{оп.мм}} = 71$ $P_{\text{н.мм}} = 200$ Гр. сл. = I Точн. = П
(ЛA2140)	ОН-3	(П39.016)	ОН-8
	$F_{\text{см}^2} = 5.251$ $Q_{\text{кз}} = 1.423$ $D_{\text{оп.мм}} = 141$ $P_{\text{н.мм}} = 578.2$ Гр. сл. = особ. Точн. = П		$F_{\text{см}^2} = 1.75$ $Q_{\text{кз}} = 0.4743$ $D_{\text{оп.мм}} = 57.5$ $P_{\text{н.мм}} = 233.4$ Гр. сл. = IV Точн. = Н
(ЛA2170)	ОН-4	(П39.026)	ОН-9
	$F_{\text{см}^2} = 5.7$ $Q_{\text{кз}} = 1.545$ $D_{\text{оп.мм}} = 172$ $P_{\text{н.мм}} = 644$ Гр. сл. = особ. Точн. = П		$F_{\text{см}^2} = 0.9299$ $Q_{\text{кз}} = 0.252$ $D_{\text{оп.мм}} = 24.2$ $P_{\text{н.мм}} = 113.2$ Гр. сл. = III Точн. = Н
(ТР-150)	ОН-5	(П39.028)	ОН-10
	$F_{\text{см}^2} = 7.44$ $Q_{\text{кз}} = 2.016$ $D_{\text{оп.мм}} = 156$ $P_{\text{н.мм}} = 380$ Гр. сл. = IV Точн. = П		$F_{\text{см}^2} = 9.84$ $Q_{\text{кз}} = 2.67$ $D_{\text{оп.мм}} = 164.1$ $P_{\text{н.мм}} = 340$ Гр. сл. = III Точн. = Н











(П39.030)	ОН-11	(П39.038)	ОН-16
	$F_{\text{с.м.}}^2 = 1.792$ $Q_{\text{кз}} = 0.486$ $D_{\text{оп.мм}} = 74.1$ $P_{\text{н.мм}} = 278$ Гр. сл. = VII Точн. = Н		$F_{\text{с.м.}}^2 = 11.13$ $Q_{\text{кз}} = 2.94$ $D_{\text{оп.мм}} = 69$ $P_{\text{н.мм}} = 205.6$ Гр. сл. = II Точн. = Н
(П39.031)	ОН-12	(П39.039)	ОН-17
	$F_{\text{с.м.}}^2 = 2.36$ $Q_{\text{кз}} = 0.64$ $D_{\text{оп.мм}} = 76$ $P_{\text{н.мм}} = 302.3$ Гр. сл. = VI Точн. = Н		$F_{\text{с.м.}}^2 = 16.7$ $Q_{\text{кз}} = 4.41$ $D_{\text{оп.мм}} = 90$ $P_{\text{н.мм}} = 262.6$ Гр. сл. = III Точн. = Н
(П39.035)	ОН-13	(П39.040)	ОН-18
	$F_{\text{с.м.}}^2 = 16.01$ $Q_{\text{кз}} = 4.24$ $D_{\text{оп.мм}} = 120.2$ $P_{\text{н.мм}} = 333.3$ Гр. сл. = II Точн. = Н		$F_{\text{с.м.}}^2 = 9.495$ $Q_{\text{кз}} = 2.5$ $D_{\text{оп.мм}} = 57.3$ $P_{\text{н.мм}} = 157.3$ Гр. сл. = I Точн. = Н
(П39.036)	ОН-14	(П39.041)	ОН-19
	$F_{\text{с.м.}}^2 = 23.2$ $Q_{\text{кз}} = 6.12$ $D_{\text{оп.мм}} = 77$ $P_{\text{н.мм}} = 290.3$ Гр. сл. = V Точн. = Н		$F_{\text{с.м.}}^2 = 3.102$ $Q_{\text{кз}} = 0.82$ $D_{\text{оп.мм}} = 52$ $P_{\text{н.мм}} = 142$ Гр. сл. = II Точн. = Н
(П39.037)	ОН-15	(П39.042)	ОН-20
	$F_{\text{с.м.}}^2 = 24.46$ $Q_{\text{кз}} = 6.49$ $D_{\text{оп.мм}} = 104$ $P_{\text{н.мм}} = 294.3$ Гр. сл. = II Точн. = Н		$F_{\text{с.м.}}^2 = 6.102$ $Q_{\text{кз}} = 1.61$ $D_{\text{оп.мм}} = 68$ $P_{\text{н.мм}} = 190.8$ Гр. сл. = II Точн. = Н











(П39.043))	ОН-21	(П39.052)	ОН-26
	$F \text{ см}^2 = 3.094$ $Q_{\text{кз}} = 0.817$ $D_{\text{оп.мм}} = 55.9$ $P_{\text{н.мм}} = 146.6$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 1.59$ $Q_{\text{кз}} = 0.42$ $D_{\text{оп.мм}} = 21$ $P_{\text{н.мм}} = 56.67$ Гр. сл. = II Точн. = Н
(П39.045)	ОН-22	(П39.057)	ОН-27
	$F \text{ см}^2 = 1.02$ $Q_{\text{кз}} = 0.278$ $D_{\text{оп.мм}} = 18$ $P_{\text{н.мм}} = 46$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 28.8$ $Q_{\text{кз}} = 7.8$ $D_{\text{оп.мм}} = 240$ $P_{\text{н.мм}} = 504$ Гр. сл. = II Точн. = Н
(П39.046)	ОН-23	(П39.061)	ОН-28
	$F \text{ см}^2 = 4.82$ $Q_{\text{кз}} = 1.31$ $D_{\text{оп.мм}} = 83.2$ $P_{\text{н.мм}} = 292.3$ Гр. сл. = IV Точн. = Н		$F \text{ см}^2 = 10.5$ $Q_{\text{кз}} = 2.846$ $D_{\text{оп.мм}} = 46.1$ $P_{\text{н.мм}} = 130.0$ Гр. сл. = I Точн. = Н
(П39.048)	ОН-24	(П39.062)	ОН-29
	$F \text{ см}^2 = 0.785$ $Q_{\text{кз}} = 0.213$ $D_{\text{оп.мм}} = 10$ $P_{\text{н.мм}} = 31.42$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 39$ $Q_{\text{кз}} = 10.57$ $D_{\text{оп.мм}} = 133.5$ $P_{\text{н.мм}} = 380$ Гр. сл. = I Точн. = Н
(П39.051)	ОН-25	(П39.066)	ОН-30
	$F \text{ см}^2 = 1.61$ $Q_{\text{кз}} = 0.43$ $D_{\text{оп.мм}} = 18$ $P_{\text{н.мм}} = 56.24$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 3.6$ $Q_{\text{кз}} = 0.976$ $D_{\text{оп.мм}} = 60.3$ $P_{\text{н.мм}} = 132$ Гр. сл. = I Точн. = Н

(П39.069)	ОН–31	(П39.076)	ОН–36
	$F \text{ см}^2 = 10.0$ $Q_{\text{кз}} = 2.71$ $D_{\text{оп.мм}} = 53.8$ $P_{\text{н.мм}} = 140$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 52.81$ $Q_{\text{кз}} = 14.312$ $D_{\text{оп.мм}} = 82$ $P_{\text{н.мм}} = 257.6$ Гр. сл. = I Точн. = Н
(П39.070)	ОН–32	(П39.077)	ОН–37
	$F \text{ см}^2 = 40$ $Q_{\text{кз}} = 10.84$ $D_{\text{оп.мм}} = 201$ $P_{\text{н.мм}} = 440$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 15.9$ $Q_{\text{кз}} = 4.3$ $D_{\text{оп.мм}} = 45$ $P_{\text{н.мм}} = 141.4$ Гр. сл. = I Точн. = Н
(П39.071)	ОН–33	(П39.007)	ОН–38
	$F \text{ см}^2 = 30$ $Q_{\text{кз}} = 8.13$ $D_{\text{оп.мм}} = 151.3$ $P_{\text{н.мм}} = 340$ Гр. сл. = I Точн. = Н		$F \text{ см}^2 = 0.82$ $Q_{\text{кз}} = 0.222$ $D_{\text{оп.мм}} = 28$ $P_{\text{н.мм}} = 164$ Гр. сл. = VI Точн. = П
(П39.074)	ОН–34	(П39.010)	ОН–39
	$F \text{ см}^2 = 6.22$ $Q_{\text{кз}} = 1.68$ $D_{\text{оп.мм}} = 37$ $P_{\text{н.мм}} = 103.9$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 0.554$ $Q_{\text{кз}} = 0.15$ $D_{\text{оп.мм}} = 18.1$ $P_{\text{н.мм}} = 48.83$ Гр. сл. = III Точн. = Н
(П39.075)	ОН–35	(П39.011)	ОН–40
	$F \text{ см}^2 = 4.224$ $Q_{\text{кз}} = 1.145$ $D_{\text{оп.мм}} = 50$ $P_{\text{н.мм}} = 113.0$ Гр. сл. = II Точн. = Н		$F \text{ см}^2 = 0.593$ $Q_{\text{кз}} = 0.16$ $D_{\text{оп.мм}} = 30$ $P_{\text{н.мм}} = 87$ Гр. сл. = VI Точн. = Н











(П39.014)	ОН-41	ОН-46
	$F \text{ см}^2 = 1.804$ $Q_{\text{кз}} = 0.499$ $D_{\text{оп.мм}} = 90.5$ $P_{\text{н.мм}} = 211.6$ Гр. сл. = V Точн. = Н	 $F \text{ см}^2 = 52.3$ $Q_{\text{кз}} = 14.2$ $D_{\text{оп.мм}} = 82.4$ $P_{\text{н.мм}} = 1916$ Гр. сл. = особ. Точн. = Н
(П39.015)	ОН-42	ОН-47
	$F \text{ см}^2 = 0.625$ $Q_{\text{кз}} = 0.17$ $D_{\text{оп.мм}} = 24.5$ $P_{\text{н.мм}} = 85.3$ Гр. сл. = III Точн. = Н	 $F \text{ см}^2 = 0.963$ $Q_{\text{кз}} = 0.261$ $D_{\text{оп.мм}} = 35.4$ $P_{\text{н.мм}} = 104.6$ Гр. сл. = III Точн. = Н
(П39.017)	ОН-43	ОН-48
	$F \text{ см}^2 = 11.54$ $Q_{\text{кз}} = 3.12$ $D_{\text{оп.мм}} = 142$ $P_{\text{н.мм}} = 543$ Гр. сл. = IV Точн. = Н	 $F \text{ см}^2 = 2.137$ $Q_{\text{кз}} = 0.579$ $D_{\text{оп.мм}} = 46.7$ $P_{\text{н.мм}} = 140.9$ Гр. сл. = III Точн. = Н
(П39.018)	ОН-44	ОН-49
	$F \text{ см}^2 = 12.41$ $Q_{\text{кз}} = 3.363$ $D_{\text{оп.мм}} = 150$ $P_{\text{н.мм}} = 515.3$ Гр. сл. = IV Точн. = Н	 $F \text{ см}^2 = 0.513$ $Q_{\text{кз}} = 0.139$ $D_{\text{оп.мм}} = 20.1$ $P_{\text{н.мм}} = 46.28$ Гр. сл. = III Точн. = Н
	ОН-45	ОН-50
	$F \text{ см}^2 = 10.0$ $Q_{\text{кз}} = 2.71$ $D_{\text{оп.мм}} = 100.5$ $P_{\text{н.мм}} = 220$ Гр. сл. = I Точн. = Н	 $F \text{ см}^2 = 0.622$ $Q_{\text{кз}} = 0.1686$ $D_{\text{оп.мм}} = 20.5$ $P_{\text{н.мм}} = 68.7$ Гр. сл. = III Точн. = Н











	ОН-51		ОН-56
	$F_{\text{с.м}^2} = 1.688$ $Q_{\text{кз}} = 0.4575$ $D_{\text{оп.мм}} = 45.3$ $P_{\text{н.мм}} = 145.6$ Гр. сл. = VI Точн. = Н		$F_{\text{с.м}^2} = 3.211$ $Q_{\text{кз}} = 0.87$ $D_{\text{оп.мм}} = 41.8$ $P_{\text{н.мм}} = 189.6$ Гр. сл. = V Точн. = Н
	ОН-52		ОН-57
	$F_{\text{с.м}^2} = 2.153$ $Q_{\text{кз}} = 0.583$ $D_{\text{оп.мм}} = 42.6$ $P_{\text{н.мм}} = 162$ Гр. сл. = III Точн. = Н		$F_{\text{с.м}^2} = 3.316$ $Q_{\text{кз}} = 0.899$ $D_{\text{оп.мм}} = 44.5$ $P_{\text{н.мм}} = 203.5$ Гр. сл. = V Точн. = Н
	ОН-53		ОН-58
	$F_{\text{с.м}^2} = 3.441$ $Q_{\text{кз}} = 0.933$ $D_{\text{оп.мм}} = 39.8$ $P_{\text{н.мм}} = 210.1$ Гр. сл. = IV Точн. = Н		$F_{\text{с.м}^2} = 1.060$ $Q_{\text{кз}} = 0.287$ $D_{\text{оп.мм}} = 29.7$ $P_{\text{н.мм}} = 110.4$ Гр. сл. = III Точн. = Н
	ОН-54		ОН-59
	$F_{\text{с.м}^2} = 2.61$ $Q_{\text{кз}} = 0.707$ $D_{\text{оп.мм}} = 36.7$ $P_{\text{н.мм}} = 173.7$ Гр. сл. = IV Точн. = Н		$F_{\text{с.м}^2} = 0.996$ $Q_{\text{кз}} = 0.27$ $D_{\text{оп.мм}} = 28.8$ $P_{\text{н.мм}} = 104.3$ Гр. сл. = III Точн. = Н
	ОН-55		ОН-60
	$F_{\text{с.м}^2} = 2.293$ $Q_{\text{кз}} = 0.621$ $D_{\text{оп.мм}} = 33.7$ $P_{\text{н.мм}} = 148.6$ Гр. сл. = IV Точн. = Н		$F_{\text{с.м}^2} = 1.21$ $Q_{\text{кз}} = 0.328$ $D_{\text{оп.мм}} = 38.1$ $P_{\text{н.мм}} = 125.5$ Гр. сл. = IV Точн. = Н










	ОН-61		ОН-66
	$F_{\text{с.м}^2} = 1.15$ $Q_{\text{кз}} = 0.312$ $D_{\text{оп.мм}} = 34.1$ $P_{\text{н.мм}} = 101.3$ Гр. сл. = IV Точн. = Н		$F_{\text{с.м}^2} = 3.233$ $Q_{\text{кз}} = 0.876$ $D_{\text{оп.мм}} = 47$ $P_{\text{н.мм}} = 199.22$ Гр. сл. = V Точн. = Н
	ОН-62		ОН-67
	$F_{\text{с.м}^2} = 8.07$ $Q_{\text{кз}} = 2.187$ $D_{\text{оп.мм}} = 79$ $P_{\text{н.мм}} = 305.3$ Гр. сл. = VII Точн. = П		$F_{\text{с.м}^2} = 3.337$ $Q_{\text{кз}} = 0.904$ $D_{\text{оп.мм}} = 50$ $P_{\text{н.мм}} = 204.7$ Гр. сл. = V Точн. = Н
	ОН-63		ОН-68
	$F_{\text{с.м}^2} = 0.965$ $Q_{\text{кз}} = 0.262$ $D_{\text{оп.мм}} = 31$ $P_{\text{н.мм}} = 90.1$ Гр. сл. = III Точн. = Н		$F_{\text{с.м}^2} = 10.18$ $Q_{\text{кз}} = 2.759$ $D_{\text{оп.мм}} = 36$ $P_{\text{н.мм}} = 113.1$ Гр. сл. = I Точн. = Н
	ОН-64		ОН-69
	$F_{\text{с.м}^2} = 0.725$ $Q_{\text{кз}} = 0.196$ $D_{\text{оп.мм}} = 24$ $P_{\text{н.мм}} = 77$ Гр. сл. = IV Точн. = П		$F_{\text{с.м}^2} = 0.434$ $Q_{\text{кз}} = 0.118$ $D_{\text{оп.мм}} = 21$ $P_{\text{н.мм}} = 51.1$ Гр. сл. = IV Точн. = Н
	ОН-65		ОН-70
	$F_{\text{с.м}^2} = 3.187$ $Q_{\text{кз}} = 0.8637$ $D_{\text{оп.мм}} = 46.6$ $P_{\text{н.мм}} = 194.7$ Гр. сл. = V Точн. = Н		$F_{\text{с.м}^2} = 2.5$ $Q_{\text{кз}} = 0.678$ $D_{\text{оп.мм}} = 50.3$ $P_{\text{н.мм}} = 110$ Гр. сл. = I Точн. = Н











	ОН-71		ОН-76
	$F_{\text{с.м}^2} = 7.863$ $Q_{\text{кз}} = 2.131$ $D_{\text{оп.мм}} = 100$ $P_{\text{н.мм}} = 209$ Гр. сл. = I Точн. = Н		$F_{\text{с.м}^2} = 7.998$ $Q_{\text{кз}} = 2.167$ $D_{\text{оп.мм}} = 80.5$ $P_{\text{н.мм}} = 179.1$ Гр. сл. = I Точн. = Н
(П39.027)	ОН-72		ОН-77
	$F_{\text{с.м}^2} = 0.714$ $Q_{\text{кз}} = 0.194$ $D_{\text{оп.мм}} = 17.5$ $P_{\text{н.мм}} = 42.4$ Гр. сл. = II Точн. = Н		$F_{\text{с.м}^2} = 2.011$ $Q_{\text{кз}} = 0.545$ $D_{\text{оп.мм}} = 16$ $P_{\text{н.мм}} = 50.26$ Гр. сл. = I Точн. = Н
	ОН-73		ОН-78
	$F_{\text{с.м}^2} = 1.037$ $Q_{\text{кз}} = 0.281$ $D_{\text{оп.мм}} = 32.13$ $P_{\text{н.мм}} = 97.64$ Гр. сл. = В Точн. = Н		$F_{\text{с.м}^2} = 2.545$ $Q_{\text{кз}} = 0.69$ $D_{\text{оп.мм}} = 18$ $P_{\text{н.мм}} = 56.55$ Гр. сл. = I Точн. = Н
	ОН-74		ОН-79
	$F_{\text{с.м}^2} = 55.504$ $Q_{\text{кз}} = 15.042$ $D_{\text{оп.мм}} = 148.7$ $P_{\text{н.мм}} = 1875$ Гр. сл. = особая Точн. = П		$F_{\text{с.м}^2} = 96.23$ $Q_{\text{кз}} = 26.08$ $D_{\text{оп.мм}} = 183$ $P_{\text{н.мм}} = 457.4$ Гр. сл. = I Точн. = Н
	ОН-75		ОН-80
	$F_{\text{с.м}^2} = 57.908$ $Q_{\text{кз}} = 15.7$ $D_{\text{оп.мм}} = 148.7$ $P_{\text{н.мм}} = 1810$ Гр. сл. = особая Точн. = П		$F_{\text{с.м}^2} = 3.14$ $Q_{\text{кз}} = 0.851$ $D_{\text{оп.мм}} = 20$ $P_{\text{н.мм}} = 62.83$ Гр. сл. = I Точн. = Н










	<p>ОН-81</p> <p> <math>F_{\text{см}^2} = 11</math>  <math>Q_{\text{кз}} = 2.981</math>  <math>D_{\text{оп.мм}} = 89.4</math>  <math>P_{\text{н.мм}} = 240</math>  Гр. сл. = II  Точн. = Н </p>		<p>ОН-86</p> <p> <math>F_{\text{см}^2} = 1.103</math>  <math>Q_{\text{кз}} = 0.299</math>  <math>D_{\text{оп.мм}} = 45.2</math>  <math>P_{\text{н.мм}} = 114</math>  Гр. сл. = IV  Точн. = Н </p>
	<p>ОН-82</p> <p> <math>F_{\text{см}^2} = 15.394</math>  <math>Q_{\text{кз}} = 4.172</math>  <math>D_{\text{оп.мм}} = 128</math>  <math>P_{\text{н.мм}} = 1056</math>  Гр. сл. = С  Точн. = Н </p>		<p>ОН-87</p> <p> <math>F_{\text{см}^2} = 4.07</math>  <math>Q_{\text{кз}} = 1.103</math>  <math>D_{\text{оп.мм}} = 62</math>  <math>P_{\text{н.мм}} = 189.8</math>  Гр. сл. = VI  Точн. = Н </p>
	<p>ОН-83</p> <p> <math>F_{\text{см}^2} = 0.76</math>  <math>Q_{\text{кз}} = 0.206</math>  <math>D_{\text{оп.мм}} = 28.28</math>  <math>P_{\text{н.мм}} = 80</math>  Гр. сл. = II  Точн. = Н </p>		<p>ОН-88</p> <p> <math>F_{\text{см}^2} = 4.212</math>  <math>Q_{\text{кз}} = 1.142</math>  <math>D_{\text{оп.мм}} = 40</math>  <math>P_{\text{н.мм}} = 136.4</math>  Гр. сл. = V  Точн. = Н </p>
	<p>ОН-84</p> <p> <math>F_{\text{см}^2} = 2.31</math>  <math>Q_{\text{кз}} = 0.626</math>  <math>D_{\text{оп.мм}} = 56.56</math>  <math>P_{\text{н.мм}} = 160</math>  Гр. сл. = III  Точн. = Н </p>		<p>ОН-89</p> <p> <math>F_{\text{см}^2} = 0.96</math>  <math>Q_{\text{кз}} = 0.26</math>  <math>D_{\text{оп.мм}} = 35.36</math>  <math>P_{\text{н.мм}} = 100</math>  Гр. сл. = III  Точн. = Н </p>
	<p>ОН-85</p> <p> <math>F_{\text{см}^2} = 33.183</math>  <math>Q_{\text{кз}} = 8.993</math>  <math>D_{\text{оп.мм}} = 65</math>  <math>P_{\text{н.мм}} = 204</math>  Гр. сл. = I  Точн. = Н </p>		<p>ОН-90</p> <p> <math>F_{\text{см}^2} = 13</math>  <math>Q_{\text{кз}} = 3.52</math>  <math>D_{\text{оп.мм}} = 100.5</math>  <math>P_{\text{н.мм}} = 223.4</math>  Гр. сл. = I  Точн. = Н </p>

	ОН-91		ОН-96
	$F_{\text{см}^2} = 5.309$ $Q_{\text{кз}} = 1.439$ $D_{\text{оп.мм}} = 26$ $P_{\text{н.мм}} = 81.68$ Гр. сл. = I Точн. = Н		$F_{\text{см}^2} = 5.505$ $Q_{\text{кз}} = 1.492$ $D_{\text{оп.мм}} = 118$ $P_{\text{н.мм}} = 401.7$ Гр. сл. = VI Точн. = Н
	ОН-92		ОН-97
	$F_{\text{см}^2} = 7.069$ $Q_{\text{кз}} = 1.916$ $D_{\text{оп.мм}} = 30$ $P_{\text{н.мм}} = 94.25$ Гр. сл. = I Точн. = Н		$F_{\text{см}^2} = 363.1$ $Q_{\text{кз}} = 98.4$ $D_{\text{оп.мм}} = 215$ $P_{\text{н.мм}} = 675.5$ Гр. сл. = I Точн. = Н
	ОН-93		ОН-98
	$F_{\text{см}^2} = 12$ $Q_{\text{кз}} = 3.252$ $D_{\text{оп.мм}} = 120.4$ $P_{\text{н.мм}} = 260$ Гр. сл. = III Точн. = Н		$F_{\text{см}^2} = 19.635$ $Q_{\text{кз}} = 5.321$ $D_{\text{оп.мм}} = 50$ $P_{\text{н.мм}} = 157.1$ Гр. сл. = I Точн. = Н
	ОН-94		ОН-99
	$F_{\text{см}^2} = 4.91$ $Q_{\text{кз}} = 1.33$ $D_{\text{оп.мм}} = 25$ $P_{\text{н.мм}} = 78.54$ Гр. сл. = I Точн. = Н		$F_{\text{см}^2} = 1.244$ $Q_{\text{кз}} = 0.337$ $D_{\text{оп.мм}} = 28$ $P_{\text{н.мм}} = 90.2$ Гр. сл. = III Точн. = Н
	ОН-95		ОН-100
	$F_{\text{см}^2} = 0.832$ $Q_{\text{кз}} = 0.2256$ $D_{\text{оп.мм}} = 23.33$ $P_{\text{н.мм}} = 82.33$ Гр. сл. = III Точн. = Н		$F_{\text{см}^2} = 9.152$ $Q_{\text{кз}} = 2.48$ $D_{\text{оп.мм}} = 98.08$ $P_{\text{н.мм}} = 637$ Гр. сл. = VI Точн. = П

	ОН-101		ОН-106
	$F, \text{см}^2 = 4.656$ $Q, \text{кг} = 1.262$ $D_{\text{оп.}}, \text{мм} = 68.4$ $P_{\text{н.}}, \text{мм} = 219.11$ Гр. сл. = IV Точн. = П		$F, \text{см}^2 = 1.6$ $Q, \text{кг} = 0.434$ $D_{\text{оп.}}, \text{мм} = 40.2$ $P_{\text{н.}}, \text{мм} = 88$ Гр. сл. = II Точн. = Н
	ОН-102		ОН-107
	$F, \text{см}^2 = 6.4$ $Q, \text{кг} = 1.734$ $D_{\text{оп.}}, \text{мм} = 80.4$ $P_{\text{н.}}, \text{мм} = 176$ Гр. сл. = I Точн. = Н		$F, \text{см}^2 = 4.8$ $Q, \text{кг} = 1.301$ $D_{\text{оп.}}, \text{мм} = 80.2$ $P_{\text{н.}}, \text{мм} = 172$ Гр. сл. = II Точн. = Н
	ОН-103		ОН-108
	$F, \text{см}^2 = 4.098$ $Q, \text{кг} = 1.111$ $D_{\text{оп.}}, \text{мм} = 58$ $P_{\text{н.}}, \text{мм} = 232.4$ Гр. сл. = VI Точн. = Н		$F, \text{см}^2 = 4.8$ $Q, \text{кг} = 1.301$ $D_{\text{оп.}}, \text{мм} = 60.5$ $P_{\text{н.}}, \text{мм} = 136$ Гр. сл. = II Точн. = Н
	ОН-104		ОН-109
	$F, \text{см}^2 = 1.341$ $Q, \text{кг} = 0.363$ $D_{\text{оп.}}, \text{мм} = 39$ $P_{\text{н.}}, \text{мм} = 95.4$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = -$ $Q, \text{кг} = -$ $D_{\text{оп.}}, \text{мм} = -$ $P_{\text{н.}}, \text{мм} = -$ Гр. сл. = — Точн. = —
	ОН-105		ОН-110
	$F, \text{см}^2 = 1.298$ $Q, \text{кг} = 0.352$ $D_{\text{оп.}}, \text{мм} = 33$ $P_{\text{н.}}, \text{мм} = 102.7$ Гр. сл. = IV Точн. = П		$F, \text{см}^2 = 4.132$ $Q, \text{кг} = 1.12$ $D_{\text{оп.}}, \text{мм} = 58.3$ $P_{\text{н.}}, \text{мм} = 206.9$ Гр. сл. = V Точн. = Н

	ОН-111		ОН-116
	$F, \text{см}^2 = 5.548$ $Q, \text{кг} = 1.504$ $D_{\text{оп}}, \text{мм} = 171.2$ $P_{\text{н}}, \text{мм} = 654.7$ Гр. сл. = Ос. Точн. = Н		$F, \text{см}^2 = 0.8$ $Q, \text{кг} = 0.217$ $D_{\text{оп}}, \text{мм} = 20.4$ $P_{\text{н}}, \text{мм} = 48$ Гр. сл. = II Точн. = Н
	ОН-112		ОН-117
	$F, \text{см}^2 = 2.0$ $Q, \text{кг} = 0.542$ $D_{\text{оп}}, \text{мм} = 40.3$ $P_{\text{н}}, \text{мм} = 90$ Гр. сл. = II Точн. = Н		$F, \text{см}^2 = 1.0$ $Q, \text{кг} = 0.271$ $D_{\text{оп}}, \text{мм} = 20.6$ $P_{\text{н}}, \text{мм} = 50.0$ Гр. сл. = II Точн. = Н
БПО-915	ОН-113		ОН-118
	$F, \text{см}^2 = 0.86$ $Q, \text{кг} = 0.233$ $D_{\text{оп}}, \text{мм} = 33.5$ $P_{\text{н}}, \text{мм} = 90$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = 0.75$ $Q, \text{кг} = 0.203$ $D_{\text{оп}}, \text{мм} = 25.2$ $P_{\text{н}}, \text{мм} = 56$ Гр. сл. = II Точн. = Н
	ОН-114		ОН-119
	$F, \text{см}^2 = 0.96$ $Q, \text{кг} = 0.26$ $D_{\text{оп}}, \text{мм} = 36.1$ $P_{\text{н}}, \text{мм} = 100$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = 3.0$ $Q, \text{кг} = 0.813$ $D_{\text{оп}}, \text{мм} = 50.4$ $P_{\text{н}}, \text{мм} = 112$ Гр. сл. = II Точн. = Н
	ОН-115		ОН-120
	$F, \text{см}^2 = 1.5$ $Q, \text{кг} = 0.407$ $D_{\text{оп}}, \text{мм} = 30.4$ $P_{\text{н}}, \text{мм} = 70$ Гр. сл. = III Точн. = Н		$F, \text{см}^2 = 14.346$ $Q, \text{кг} = 3.888$ $D_{\text{оп}}, \text{мм} = 120.2$ $P_{\text{н}}, \text{мм} = 259.7$ Гр. сл. = II Точн. = Н

	ОН-121		ОН-126
	$F, \text{см}^2 = -$ $Q, \text{кг} = -$ $D_{\text{оп}}, \text{мм} = -$ $P_{\text{н}}, \text{мм} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$		$F, \text{см}^2 = 1.2$ $Q, \text{кг} = 0.325$ $D_{\text{оп}}, \text{мм} = 40.1$ $P_{\text{н}}, \text{мм} = 86$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	ОН-122		ОН-127
	$F, \text{см}^2 = 3.2$ $Q, \text{кг} = 0.867$ $D_{\text{оп}}, \text{мм} = 40.8$ $P_{\text{н}}, \text{мм} = 96$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = 1.2$ $Q, \text{кг} = 0.325$ $D_{\text{оп}}, \text{мм} = 30.3$ $P_{\text{н}}, \text{мм} = 68$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	ОН-123		ОН-128
	$F, \text{см}^2 = 3.0$ $Q, \text{кг} = 0.813$ $D_{\text{оп}}, \text{мм} = 60.2$ $P_{\text{н}}, \text{мм} = 130$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = 0.56$ $Q, \text{кг} = 0.152$ $D_{\text{оп}}, \text{мм} = 21.2$ $P_{\text{н}}, \text{мм} = 60$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
БПО-1908	ОН-124		ОН-129
	$F, \text{см}^2 = 12.38$ $Q, \text{кг} = 3.355$ $D_{\text{оп}}, \text{мм} = 125$ $P_{\text{н}}, \text{мм} = 744.3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = -$ $Q, \text{кг} = -$ $D_{\text{оп}}, \text{мм} = -$ $P_{\text{н}}, \text{мм} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	ОН-125		ОН-130
	$F, \text{см}^2 = 2.0$ $Q, \text{кг} = 0.542$ $D_{\text{оп}}, \text{мм} = 50.2$ $P_{\text{н}}, \text{мм} = 108$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = -$ $Q, \text{кг} = -$ $D_{\text{оп}}, \text{мм} = -$ $P_{\text{н}}, \text{мм} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$