





























































	ЗК-1	(100054)	ЗК-6
	$F \text{ см}^2 = 7.06$ $Q \text{ кг} = 1.91$ $D \text{ оп.мм} = 140.2$ $P \text{ н.мм} = 373.8$ $P \text{ в.мм} = 103.2$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$		$F \text{ см}^2 = 4.921$ $Q \text{ кг} = 1.334$ $D \text{ оп.мм} = 75.1$ $P \text{ н.мм} = 302.9$ $P \text{ в.мм} = 178.9$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$
	ЗК-2	(ЯВ-2)	ЗК-7
	$F \text{ см}^2 = 6.021$ $Q \text{ кг} = 1.632$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 342.1$ $P \text{ в.мм} = 142.5$ $\Gamma \text{ р. сл.} = \text{ОСОБ}$ $\text{Точн.} = П$		$F \text{ см}^2 = 0.901$ $Q \text{ кг} = 0.244$ $D \text{ оп.мм} = 15$ $P \text{ н.мм} = 47.1$ $P \text{ в.мм} = 33$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$
	ЗК-3	(РОСТ-10)	ЗК-8
	$F \text{ см}^2 = 4.52$ $Q \text{ кг} = 1.225$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 287$ $P \text{ в.мм} = 107.3$ $\Gamma \text{ р. сл.} = \text{ОСОБ}$ $\text{Точн.} = П$		$F \text{ см}^2 = 1.76$ $Q \text{ кг} = 0.477$ $D \text{ оп.мм} = 37$ $P \text{ н.мм} = 126$ $P \text{ в.мм} = 36$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$
	ЗК-4	(РДГ-79)	ЗК-9
	$F \text{ см}^2 = 7.23$ $Q \text{ кг} = 1.96$ $D \text{ оп.мм} = 126.3$ $P \text{ н.мм} = 309.2$ $P \text{ в.мм} = 26.4$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 6.402$ $Q \text{ кг} = 1.735$ $D \text{ оп.мм} = 106$ $P \text{ н.мм} = 312$ $P \text{ в.мм} =$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$
(100005)	ЗК-5	(В75.10)	ЗК-10
	$F \text{ см}^2 = 13.28$ $Q \text{ кг} = 3.6$ $D \text{ оп.мм} = 184.2$ $P \text{ н.мм} = 624.6$ $P \text{ в.мм} = 379.9$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 20.42$ $Q \text{ кг} = 5.534$ $D \text{ оп.мм} = 75$ $P \text{ н.мм} = 235.6$ $P \text{ в.мм} = 172.8$ $\Gamma \text{ р. сл.} = I$ $\text{Точн.} = H$











(Б-59)	ЗК-11	(100009)	ЗК-16
	$F \text{ см}^2 = 4.129$ $Q \text{ кг} = 1.119$ $D \text{ оп.мм} = 62$ $P \text{ н.мм} = 196.1$ $P \text{ в.мм} = 164.2$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 7.31$ $Q \text{ кг} = 1.981$ $D \text{ оп.мм} = 109.7$ $P \text{ н.мм} = 377.4$ $P \text{ в.мм} = 253.5$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
(ПР-40)	ЗК-12		ЗК-17
	$F \text{ см}^2 = 3.75$ $Q \text{ кг} = 1.016$ $D \text{ оп.мм} = 43.4$ $P \text{ н.мм} = 309.4$ $P \text{ в.мм} = 62.8$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 1.618$ $Q \text{ кг} = 0.439$ $D \text{ оп.мм} = 41.4$ $P \text{ н.мм} = 164.7$ $P \text{ в.мм} =$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
(ПР-60)	ЗК-13		ЗК-18
	$F \text{ см}^2 = 3.03$ $Q \text{ кг} = 0.821$ $D \text{ оп.мм} = 63$ $P \text{ н.мм} = 209.7$ $P \text{ в.мм} = 94$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 1.84$ $Q \text{ кг} = 0.499$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100$ $P \text{ в.мм} = 84$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{H}$
(Т-1)	ЗК-14		ЗК-19
	$F \text{ см}^2 = 1.347$ $Q \text{ кг} = 0.365$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 96.3$ $P \text{ в.мм} = 83.1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3.513$ $Q \text{ кг} = 0.952$ $D \text{ оп.мм} = 76$ $P \text{ н.мм} = 244$ $P \text{ в.мм} = 62.9$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$
(Т-18)	ЗК-15		ЗК-20
	$F \text{ см}^2 = 0.864$ $Q \text{ кг} = 0.234$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 72.3$ $P \text{ в.мм} = 60.7$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 2.464$ $Q \text{ кг} = 0.668$ $D \text{ оп.мм} = 34.5$ $P \text{ н.мм} = 134.2$ $P \text{ в.мм} = 63.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$











	3К-21	(C9)	3К-26
	$F \text{ см}^2 = 2,64$ $Q \text{ кг} = 0,715$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78,5$ $P \text{ в.мм} = 53,4$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 11,94$ $Q \text{ кг} = 3,236$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 160,3$ $P \text{ в.мм} = 99$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
(C5)	3К-22	(C10)	3К-27
	$F \text{ см}^2 = 14,61$ $Q \text{ кг} = 3,959$ $D \text{ оп.мм} = 54$ $P \text{ н.мм} = 165,5$ $P \text{ в.мм} = 88$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 21,55$ $Q \text{ кг} = 5,84$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 201$ $P \text{ в.мм} = 110$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
(C6)	3К-23	(C11)	3К-28
	$F \text{ см}^2 = 17,04$ $Q \text{ кг} = 4,618$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 179,4$ $P \text{ в.мм} = 99$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 14,896$ $Q \text{ кг} = 4,037$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 160,3$ $P \text{ в.мм} = 99$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
(C7)	3К-24		3К-29
	$F \text{ см}^2 = 9,89$ $Q \text{ кг} = 2,68$ $D \text{ оп.мм} = 80$ $P \text{ н.мм} = 251,3$ $P \text{ в.мм} = 225,3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4,43$ $Q \text{ кг} = 1,201$ $D \text{ оп.мм} = 43,3$ $P \text{ н.мм} = 342$ $P \text{ в.мм} = 83,9$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
(C8)	3К-25		3К-30
	$F \text{ см}^2 = 18,22$ $Q \text{ кг} = 4,939$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 179,4$ $P \text{ в.мм} = 91,1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 85,23$ $Q, \text{ кг} = 23,1$ $D \text{ оп.мм} = 167,6$ $P \text{ н.мм} = 496,4$ $P \text{ в.мм} = 320,7$ $\Gamma \text{р. сл.} = \text{Особ.}$ $\text{Точн.} = \text{П}$

	3К-31		3К-36
	$F, \text{ см}^2 = 2,462$ $Q, \text{ кг} = 0,667$ $D_{\text{оп.мм}} = 47,1$ $P_{\text{н.мм}} = 171,5$ $P_{\text{в.мм}} = 44,3$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 2,52$ $Q \text{ кг} = 0,683$ $D_{\text{оп.мм}} = 52,3$ $P_{\text{н.мм}} = 226,4$ $P_{\text{в.мм}} = 65,5$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \Pi$
	3К-32		3К-37
	$F, \text{ см}^2 = 1,592$ $Q, \text{ кг} = 0,43$ $D_{\text{оп.мм}} = 40$ $P_{\text{н.мм}} = 110,9$ $P_{\text{в.мм}} = 101,4$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 7,67$ $Q \text{ кг} = 2,08$ $D_{\text{оп.мм}} = 129,7$ $P_{\text{н.мм}} = 388$ $P_{\text{в.мм}} = 212$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \text{H}$
	3К-33		3К-38
	$F, \text{ см}^2 = 8,7$ $Q, \text{ кг} = 2,358$ $D_{\text{оп.мм}} = 55$ $P_{\text{н.мм}} = 315$ $P_{\text{в.мм}} = 22$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 6,1585$ $Q \text{ кг} = 1,668$ $D_{\text{оп.мм}} = 83,5$ $P_{\text{н.мм}} = 349,6$ $P_{\text{в.мм}} = 167,7$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \Pi$
	3К-34		3К-39
	$F \text{ см}^2 = 4,79$ $Q \text{ кг} = 1,3$ $D_{\text{оп.мм}} = 43,3$ $P_{\text{н.мм}} = 339$ $P_{\text{в.мм}} = 65,4$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 2,285$ $Q \text{ кг} = 0,617$ $D_{\text{оп.мм}} = 26,7$ $P_{\text{н.мм}} = 108,4$ $P_{\text{в.мм}} = 26,4$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \text{H}$
	3К-35		3К-40
	$F \text{ см}^2 = 3,03$ $Q \text{ кг} = 0,821$ $D_{\text{оп.мм}} = 52,5$ $P_{\text{н.мм}} = 240$ $P_{\text{в.мм}} = 65,1$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 3,076$ $Q \text{ кг} = 0,834$ $D_{\text{оп.мм}} = 70$ $P_{\text{н.мм}} = 161,8$ $P_{\text{в.мм}} = 145,8$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$











	3К-41		3К-46
	$F \text{ см}^2 = 14,45$ $Q \text{ кг} = 3,916$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 202$ $P \text{ в.мм} = 147,7$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 5,944$ $Q \text{ кг} = 1,61$ $D \text{ оп.мм} = 51,9$ $P \text{ н.мм} = 331,7$ $P \text{ в.мм} = 140$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{H}$
	3К-42		3К-47
	$F \text{ см}^2 = 4,7$ $Q \text{ кг} = 1,274$ $D \text{ оп.мм} = 86$ $P \text{ н.мм} = 272$ $P \text{ в.мм} = 198$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4,89$ $Q \text{ кг} = 1,325$ $D \text{ оп.мм} = 67,5$ $P \text{ н.мм} = 285,7$ $P \text{ в.мм} = 85,6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
	3К-43		3К-48
	$F \text{ см}^2 = 14,74$ $Q \text{ кг} = 3,995$ $D \text{ оп.мм} = 203,3$ $P \text{ н.мм} = 795$ $P \text{ в.мм} = 202,6$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{ОСОВЯ}$		$F \text{ см}^2 = 7,24$ $Q \text{ кг} = 1,962$ $D \text{ оп.мм} = 117$ $P \text{ н.мм} = 351,8$ $P \text{ в.мм} = 178$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
	3К-44		3К-49
	$F \text{ см}^2 = 11,65$ $Q \text{ кг} = 3,157$ $D \text{ оп.мм} = 147,3$ $P \text{ н.мм} = 615,5$ $P \text{ в.мм} = 202,6$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{ОВОВЯ}$		$F \text{ см}^2 = 34,88$ $Q \text{ кг} = 9,452$ $D \text{ оп.мм} = 206$ $P \text{ н.мм} = 809,8$ $P \text{ в.мм} = 384$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$
	3К-45		3К-50
	$F \text{ см}^2 = 3,253$ $Q \text{ кг} = 0,881$ $D \text{ оп.мм} = 57$ $P \text{ н.мм} = 170$ $P \text{ в.мм} = 156$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 30,1$ $Q \text{ кг} = 8,157$ $D \text{ оп.мм} = 150$ $P \text{ н.мм} = 1024$ $P \text{ в.мм} = 320,6$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$

	3К-51		3К-56
	$F \text{ см}^2 = 7.277$ $Q \text{ кг} = 1.972$ $D \text{ оп.мм} = 86.5$ $P \text{ н.мм} = 296.9$ $P \text{ в.мм} = 156.6$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 5.7$ $Q \text{ кг} = 1.55$ $D \text{ оп.мм} = 108.5$ $P \text{ н.мм} = 481.5$ $P \text{ в.мм} =$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	3К-52		3К-57
	$F \text{ см}^2 = 4.58$ $Q \text{ кг} = 1.237$ $D \text{ оп.мм} = 16.5$ $P \text{ н.мм} = 91$ $P \text{ в.мм} = 38.17$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 2.758$ $Q \text{ кг} = 0.745$ $D \text{ оп.мм} = 29.7$ $P \text{ н.мм} = 198.1$ $P \text{ в.мм} = 28$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	3К-53		3К-58
	$F \text{ см}^2 = 3.052$ $Q \text{ кг} = 0.827$ $D \text{ оп.мм} = 84.84$ $P \text{ н.мм} = 240$ $P \text{ в.мм} = 230.4$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 12.052$ $Q \text{ кг} = 3.266$ $D \text{ оп.мм} = 126.5$ $P \text{ н.мм} = 536.2$ $P \text{ в.мм} = 614$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$
	3К-54		3К-59
	$F \text{ см}^2 = 6.97$ $Q \text{ кг} = 1.89$ $D \text{ оп.мм} = 177$ $P \text{ н.мм} = 555$ $P \text{ в.мм} = 132$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{А}$		$F \text{ см}^2 = 5.31$ $Q \text{ кг} = 1.439$ $D \text{ оп.мм} = 56.57$ $P \text{ н.мм} = 281.6$ $P \text{ в.мм} = 233.3$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$
	3К-55		3К-60
	$F \text{ см}^2 = 4.24$ $Q \text{ кг} = 1.15$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 354.4$ $P \text{ в.мм} = 66$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 19.4$ $Q \text{ кг} = 5.257$ $D \text{ оп.мм} = 110.4$ $P \text{ н.мм} = 292$ $P \text{ в.мм} = 276.1$ $\Gamma \text{р. сл.} = \text{осб.}$ $\text{Точн.} = \text{П}$











	3К-61		3К-66
	<p> <math>F \text{ см}^2 = 4,73</math>  <math>Q \text{ кг} = 1,282</math>  <math>D_{\text{оп.мм}} = 55,8</math>  <math>P_{\text{н.мм}} = 147</math>  <math>P_{\text{в.мм}} = 140</math>  <math>\Gamma_{\text{р. сл.}} = \text{ОСБ}</math>  <math>\text{Точн.} = \Pi</math> </p>		<p> <math>F \text{ см}^2 = 3,672</math>  <math>Q \text{ кг} = 0,995</math>  <math>D_{\text{оп.мм}} = 85,14</math>  <math>P_{\text{н.мм}} = 244</math>  <math>P_{\text{в.мм}} = 146</math>  <math>\Gamma_{\text{р. сл.}} = V</math>  <math>\text{Точн.} = H</math> </p>
	3К-62		3К-67
	<p> <math>F \text{ см}^2 = 9,432</math>  <math>Q \text{ кг} = 2,556</math>  <math>D_{\text{оп.мм}} = 80,5</math>  <math>P_{\text{н.мм}} = 213</math>  <math>P_{\text{в.мм}} = 208</math>  <math>\Gamma_{\text{р. сл.}} = \text{ОСБ}</math>  <math>\text{Точн.} = \Pi</math> </p>		<p> <math>F, \text{ см}^2 = 11,019</math>  <math>Q, \text{ кг} = 2,986</math>  <math>D_{\text{оп.мм}} = 80</math>  <math>P_{\text{н.мм}} = 552,7</math>  <math>P_{\text{вн.мм}} = 478,2</math>  <math>\Gamma_{\text{р. сл.}} = VII</math>  <math>\text{Точн.} = H</math> </p>
	3К-63		3К-68
	<p> <math>F \text{ см}^2 = 3,205</math>  <math>Q \text{ кг} = 0,869</math>  <math>D_{\text{оп.мм}} = 28,62</math>  <math>P_{\text{н.мм}} = 91</math>  <math>P_{\text{в.мм}} = 72</math>  <math>\Gamma_{\text{р. сл.}} = B</math>  <math>\text{Точн.} = H</math> </p>		<p> <math>F, \text{ см}^2 = 2,323</math>  <math>Q, \text{ кг} = 0,629</math>  <math>D_{\text{оп.мм}} = 30</math>  <math>P_{\text{н.мм}} = 81,91</math>  <math>P_{\text{вн.мм}} = 19,16</math>  <math>\Gamma_{\text{р. сл.}} = III</math>  <math>\text{Точн.} = \Pi</math> </p>
	3К-64		3К-69
	<p> <math>F \text{ см}^2 = 21,206</math>  <math>Q \text{ кг} = 5,749</math>  <math>D_{\text{оп.мм}} = 140</math>  <math>P_{\text{н.мм}} = 440</math>  <math>P_{\text{в.мм}} = 408</math>  <math>\Gamma_{\text{р. сл.}} = C</math>  <math>\text{Точн.} = H</math> </p>		<p> <math>F, \text{ см}^2 = 2,233</math>  <math>Q, \text{ кг} = 0,605</math>  <math>D_{\text{оп.мм}} = 33,48</math>  <math>P_{\text{н.мм}} = 98,15</math>  <math>P_{\text{вн.мм}} = 19,16</math>  <math>\Gamma_{\text{р. сл.}} = III</math>  <math>\text{Точн.} = \Pi</math> </p>
	3К-65		3К-70
	<p> <math>F \text{ см}^2 = 8,77</math>  <math>Q \text{ кг} = 2,377</math>  <math>D_{\text{оп.мм}} = 207</math>  <math>P_{\text{н.мм}} = 457</math>  <math>P_{\text{в.мм}} = 1720</math>  <math>\Gamma_{\text{р. сл.}} = VI</math>  <math>\text{Точн.} = H</math> </p>		<p> <math>F, \text{ см}^2 = 7,058</math>  <math>Q, \text{ кг} = 1,913</math>  <math>D_{\text{оп.мм}} = 126,3</math>  <math>P_{\text{н.мм}} = 340,1</math>  <math>P_{\text{вн.мм}} = 26,4</math>  <math>\Gamma_{\text{р. сл.}} = V</math>  <math>\text{Точн.} = \Pi</math> </p>

	<p>3K-71</p> <p><math>F, \text{см}^2 = 6.103</math>  <math>Q, \text{кг} = 1.654</math>  <math>D_{\text{оп,мм}} = 53.5</math>  <math>P_{\text{н,мм}} = 264.5</math>  <math>P_{\text{вн,мм}} = 60.8</math>  <math>\Gamma_{\text{р. сл.}} = \text{ОС.}</math>  <math>\text{Точн.} = \text{Н}</math></p>		<p>3K-76</p> <p><math>F, \text{см}^2 = 4.139</math>  <math>Q, \text{кг} = 1.122</math>  <math>D_{\text{оп,мм}} = 96</math>  <math>P_{\text{н,мм}} = 226.9</math>  <math>P_{\text{вн,мм}} = 71.7</math>  <math>\Gamma_{\text{р. сл.}} = \text{IV}</math>  <math>\text{Точн.} = \text{Н}</math></p>
	<p>3K-72</p> <p><math>F, \text{см}^2 = 5.05</math>  <math>Q, \text{кг} = 1.369</math>  <math>D_{\text{оп,мм}} = 97.83</math>  <math>P_{\text{н,мм}} = 344</math>  <math>P_{\text{вн,мм}} = 176</math>  <math>\Gamma_{\text{р. сл.}} = \text{IV}</math>  <math>\text{Точн.} = \text{Н}</math></p>		<p>3K-77</p> <p><math>F, \text{см}^2 = 6.506</math>  <math>Q, \text{кг} = 1.763</math>  <math>D_{\text{оп,мм}} = 56.4</math>  <math>P_{\text{н,мм}} = 301.4</math>  <math>P_{\text{вн,мм}} = 95.7</math>  <math>\Gamma_{\text{р. сл.}} = \text{ОС.}</math>  <math>\text{Точн.} = \text{Н}</math></p>
	<p>3K-73</p> <p><math>F, \text{см}^2 = 2.711</math>  <math>Q, \text{кг} = 0.735</math>  <math>D_{\text{оп,мм}} = 47.1</math>  <math>P_{\text{н,мм}} = 175.7</math>  <math>P_{\text{вн,мм}} = 31.34</math>  <math>\Gamma_{\text{р. сл.}} = \text{VII}</math>  <math>\text{Точн.} = \text{П}</math></p>		<p>3K-78</p> <p><math>F, \text{см}^2 = 15.592</math>  <math>Q, \text{кг} = 4.225</math>  <math>D_{\text{оп,мм}} = 96.4</math>  <math>P_{\text{н,мм}} = 326.6</math>  <math>P_{\text{вн,мм}} = 339</math>  <math>\Gamma_{\text{р. сл.}} = \text{V}</math>  <math>\text{Точн.} = \text{Н}</math></p>
	<p>3K-74</p> <p><math>F, \text{см}^2 = 8.395</math>  <math>Q, \text{кг} = 2.275</math>  <math>D_{\text{оп,мм}} = 131</math>  <math>P_{\text{н,мм}} = 424</math>  <math>P_{\text{вн,мм}} = 451</math>  <math>\Gamma_{\text{р. сл.}} = \text{ОСОВ.}</math>  <math>\text{Точн.} = \text{П}</math></p>		<p>3K-79</p> <p><math>F, \text{см}^2 = 19.573</math>  <math>Q, \text{кг} = 5.304</math>  <math>D_{\text{оп,мм}} = 113.14</math>  <math>P_{\text{н,мм}} = 530</math>  <math>P_{\text{вн,мм}} = 397</math>  <math>\Gamma_{\text{р. сл.}} = \text{ОС}</math>  <math>\text{Точн.} = \text{Н}</math></p>
	<p>3K-75</p> <p><math>F, \text{см}^2 = 12.978</math>  <math>Q, \text{кг} = 3.519</math>  <math>D_{\text{оп,мм}} = 103.11</math>  <math>P_{\text{н,мм}} = 423.5</math>  <math>P_{\text{вн,мм}} = 91.6</math>  <math>\Gamma_{\text{р. сл.}} = \text{VII}</math>  <math>\text{Точн.} = \text{П}</math></p>		<p>3K-80</p> <p><math>F, \text{см}^2 = 5.107</math>  <math>Q, \text{кг} = 1.384</math>  <math>D_{\text{оп,мм}} = 59.8</math>  <math>P_{\text{н,мм}} = 207.9</math>  <math>P_{\text{вн,мм}} = 169.2</math>  <math>\Gamma_{\text{р. сл.}} = \text{VI}</math>  <math>\text{Точн.} = \text{Н}</math></p>



















	3К-81		3К-86
	$F, \text{ см}^2 = 1564$ $Q, \text{ кг} = 0.424$ $D_{\text{оп.,мм}} = 42.3$ $P_{\text{н.,мм}} = 109$ $P_{\text{вн.,мм}} = 99.6$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 3.394$ $Q, \text{ кг} = 0.92$ $D_{\text{оп.,мм}} = 50$ $P_{\text{н.,мм}} = 176.85$ $P_{\text{вн.,мм}} = 49.4$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{Н}$
	3К-82		3К-87
	$F, \text{ см}^2 = 6.122$ $Q, \text{ кг} = 1.66$ $D_{\text{оп.,мм}} = 65$ $P_{\text{н.,мм}} = 171.9$ $P_{\text{вн.,мм}} = 104.6$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 10.832$ $Q, \text{ кг} = 2.935$ $D_{\text{оп.,мм}} = 80$ $P_{\text{н.,мм}} = 538.2$ $P_{\text{вн.,мм}} = 478.2$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \text{Н}$
	3К-83		3К-88
	$F, \text{ см}^2 = 4.704$ $Q, \text{ кг} = 1.275$ $D_{\text{оп.,мм}} = 79$ $P_{\text{н.,мм}} = 236$ $P_{\text{вн.,мм}} = 77.4$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 19.524$ $Q, \text{ кг} = 5.291$ $D_{\text{оп.,мм}} = 113.14$ $P_{\text{н.,мм}} = 519.9$ $P_{\text{вн.,мм}} = 397$ $\Gamma_{\text{р. сл.}} = \text{OC.}$ $\text{Точн.} = \text{Н}$
	3К-84		3К-89
	$F, \text{ см}^2 = 17.598$ $Q, \text{ кг} = 4.769$ $D_{\text{оп.,мм}} = 150$ $P_{\text{н.,мм}} = 754$ $P_{\text{вн.,мм}} = 258$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 1.119$ $Q, \text{ кг} = 0.303$ $D_{\text{оп.,мм}} = 30$ $P_{\text{н.,мм}} = 79.3$ $P_{\text{вн.,мм}} = 69.9$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{Н}$
	3К-85		3К-90
	$F, \text{ см}^2 = 8.1$ $Q, \text{ кг} = 2.195$ $D_{\text{оп.,мм}} = 90.5$ $P_{\text{н.,мм}} = 317.7$ $P_{\text{вн.,мм}} = 122.4$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 1.442$ $Q, \text{ кг} = 0.319$ $D_{\text{оп.,мм}} = 43.5$ $P_{\text{н.,мм}} = 100.8$ $P_{\text{вн.,мм}} = 91.4$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{Н}$











	3К-91		3К-96
	$F, \text{ см}^2 = 5.159$ $Q, \text{ кг} = 1.398$ $D_{\text{оп.,мм}} = 80.3$ $P_{\text{н.,мм}} = 274.2$ $P_{\text{вн.,мм}} = 262.2$ $\Gamma_{\text{р. сл.}} = 0 \text{ соб.}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 2.191$ $Q, \text{ кг} = 0.594$ $D_{\text{оп.,мм}} = 20$ $P_{\text{н.,мм}} = 62.8$ $P_{\text{вн.,мм}} = 34.6$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	3К-92		3К-97
	$F, \text{ см}^2 = 7.775$ $Q, \text{ кг} = 2.107$ $D_{\text{оп.,мм}} = 83.4$ $P_{\text{н.,мм}} = 476.1$ $P_{\text{вн.,мм}} = 112.4$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 4.019$ $Q, \text{ кг} = 1.089$ $D_{\text{оп.,мм}} = 28$ $P_{\text{н.,мм}} = 88.0$ $P_{\text{вн.,мм}} = 51.8$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	3К-93		3К-98
	$F, \text{ см}^2 = 4.009$ $Q, \text{ кг} = 1.086$ $D_{\text{оп.,мм}} = 58$ $P_{\text{н.,мм}} = 258.4$ $P_{\text{вн.,мм}} = 136.8$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \square \text{ с.}$		$F, \text{ см}^2 = 5.466$ $Q, \text{ кг} = 1.481$ $D_{\text{оп.,мм}} = 35$ $P_{\text{н.,мм}} = 110$ $P_{\text{вн.,мм}} = 72.1$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	3К-94		3К-99
	$F, \text{ см}^2 = 2.095$ $Q, \text{ кг} = 0.568$ $D_{\text{оп.,мм}} = 38.9$ $P_{\text{н.,мм}} = 95.8$ $P_{\text{вн.,мм}} = 25.1$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп.,мм}} = -$ $P_{\text{н.,мм}} = -$ $P_{\text{вн.,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	3К-95		3К-100
	$F, \text{ см}^2 = 3.958$ $Q, \text{ кг} = 1.073$ $D_{\text{оп.,мм}} = 45$ $P_{\text{н.,мм}} = 141.4$ $P_{\text{вн.,мм}} = 122.5$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп.,мм}} = -$ $P_{\text{н.,мм}} = -$ $P_{\text{вн.,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$

	<p>3K-101</p> <p><math>F, \text{см}^2 = 9.524</math>  <math>Q, \text{кг} = 2.581</math>  <math>D_{\text{оп,мм}} = 146.4</math>  <math>P_{\text{н,мм}} = 552.9</math>  <math>P_{\text{вн,мм}} = 302.6</math>  <math>\Gamma_{\text{р. сл.}} = \vee \text{I}</math>  <math>\text{Точн.} = \text{H}</math></p>		<p>3K-106</p> <p><math>F, \text{см}^2 = 14.65</math>  <math>Q, \text{кг} = 3.97</math>  <math>D_{\text{оп,мм}} = 27.3</math>  <math>P_{\text{н,мм}} = 338.2</math>  <math>P_{\text{вн,мм}} = 229.5</math>  <math>\Gamma_{\text{р. сл.}} = \vee</math>  <math>\text{Точн.} = \text{H}</math></p>
	<p>3K-102</p> <p><math>F, \text{см}^2 = 8.56</math>  <math>Q, \text{кг} = 2.32</math>  <math>D_{\text{оп,мм}} = 123.2</math>  <math>P_{\text{н,мм}} = 504.7</math>  <math>P_{\text{вн,мм}} = 254.4</math>  <math>\Gamma_{\text{р. сл.}} = \vee \text{I}</math>  <math>\text{Точн.} = \text{H}</math></p>		<p>3K-107</p> <p><math>F, \text{см}^2 = 6.479</math>  <math>Q, \text{кг} = 1.756</math>  <math>D_{\text{оп,мм}} = 115.76</math>  <math>P_{\text{н,мм}} = 337.4</math>  <math>P_{\text{вн,мм}} = 300</math>  <math>\Gamma_{\text{р. сл.}} = \vee</math>  <math>\text{Точн.} = \text{H}</math></p>
	<p>3K-103</p> <p><math>F, \text{см}^2 = 7.596</math>  <math>Q, \text{кг} = 2.059</math>  <math>D_{\text{оп,мм}} = 100.5</math>  <math>P_{\text{н,мм}} = 456.5</math>  <math>P_{\text{вн,мм}} = 206.2</math>  <math>\Gamma_{\text{р. сл.}} = \vee \text{I}</math>  <math>\text{Точн.} = \text{H}</math></p>		<p>3K-108</p> <p><math>F, \text{см}^2 = 19.094</math>  <math>Q, \text{кг} = 5.175</math>  <math>D_{\text{оп,мм}} = 109</math>  <math>P_{\text{н,мм}} = 375.1</math>  <math>P_{\text{вн,мм}} = 456.9</math>  <math>\Gamma_{\text{р. сл.}} = \vee \text{I}</math>  <math>\text{Точн.} = \Pi</math></p>
	<p>3K-104</p> <p><math>F, \text{см}^2 = 5.33</math>  <math>Q, \text{кг} = 1.444</math>  <math>D_{\text{оп,мм}} = 98.7</math>  <math>P_{\text{н,мм}} = 365.5</math>  <math>P_{\text{вн,мм}} = 238.4</math>  <math>\Gamma_{\text{р. сл.}} = \vee \text{I}</math>  <math>\text{Точн.} = \text{H}</math></p>		<p>3K-109</p> <p><math>F, \text{см}^2 = 17.98</math>  <math>Q, \text{кг} = 4.873</math>  <math>D_{\text{оп,мм}} = 36.1</math>  <math>P_{\text{н,мм}} = 257.5</math>  <math>P_{\text{вн,мм}} = 197.3</math>  <math>\Gamma_{\text{р. сл.}} = \vee</math>  <math>\text{Точн.} = \text{H}</math></p>
	<p>3K-105</p> <p><math>F, \text{см}^2 = 4.31</math>  <math>Q, \text{кг} = 1.168</math>  <math>D_{\text{оп,мм}} = 72.1</math>  <math>P_{\text{н,мм}} = 305.5</math>  <math>P_{\text{вн,мм}} = 178.4</math>  <math>\Gamma_{\text{р. сл.}} = \vee \text{I}</math>  <math>\text{Точн.} = \text{H}</math></p>		<p>3K-110</p> <p><math>F, \text{см}^2 = 17.78</math>  <math>Q, \text{кг} = 4.82</math>  <math>D_{\text{оп,мм}} = 80.85</math>  <math>P_{\text{н,мм}} = 238</math>  <math>P_{\text{вн,мм}} = 157.1</math>  <math>\Gamma_{\text{р. сл.}} = \text{I} \vee</math>  <math>\text{Точн.} = \text{H}</math></p>

	ЗК-111		ЗК-116
	$F, \text{ см}^2 = 8.246$ $Q, \text{ кг} = 2.235$ $D_{\text{оп,мм}} = 103.6$ $P_{\text{н,мм}} = 344$ $P_{\text{вн,мм}} = 148.7$ $\Gamma_{\text{р. сл.}} = IV$ $\text{Точн.} = Н$		$F, \text{ см}^2 = 4.00$ $Q, \text{ кг} = 1.083$ $D_{\text{оп,мм}} = 54.3$ $P_{\text{н,мм}} = 243.2$ $P_{\text{вн,мм}} = 69.1$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = Н$
	ЗК-112		ЗК-117
	$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп,мм}} = -$ $P_{\text{н,мм}} = -$ $P_{\text{вн,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп,мм}} = -$ $P_{\text{н,мм}} = -$ $P_{\text{вн,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	ЗК-113		ЗК-118
	$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп,мм}} = -$ $P_{\text{н,мм}} = -$ $P_{\text{вн,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп,мм}} = -$ $P_{\text{н,мм}} = -$ $P_{\text{вн,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	ЗК-114		ЗК-119
	$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп,мм}} = -$ $P_{\text{н,мм}} = -$ $P_{\text{вн,мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$		$F, \text{ см}^2 = 3.135$ $Q, \text{ кг} = 0.85$ $D_{\text{оп,мм}} = 43$ $P_{\text{н,мм}} = 109.6$ $P_{\text{вн,мм}} = 105.7$ $\Gamma_{\text{р. сл.}} = OC.$ $\text{Точн.} = П$
	ЗК-115		ЗК-120
	$F, \text{ см}^2 = 1.541$ $Q, \text{ кг} = 0.418$ $D_{\text{оп,мм}} = 42.5$ $P_{\text{н,мм}} = 115.3$ $P_{\text{вн,мм}} = 50.3$ $\Gamma_{\text{р. сл.}} = V$ $\text{Точн.} = Н$		$F, \text{ см}^2 = 4.843$ $Q, \text{ кг} = 1.312$ $D_{\text{оп,мм}} = 51$ $P_{\text{н,мм}} = 235.2$ $P_{\text{вн,мм}} = 71.5$ $\Gamma_{\text{р. сл.}} = VI$ $\text{Точн.} = Н$











	3К-121		3К-126
	$F, \text{ см}^2 = 8,727$ $Q, \text{ кг} = 2,356$ $D_{\text{оп,мм}} = 67,07$ $P_{\text{н,мм}} = 176,3$ $P_{\text{вн,мм}} = 170,2$ Гр. сл. = ОСБ Точн. = П		$F, \text{ см}^2 = 4,00$ $Q, \text{ кг} = 1,083$ $D_{\text{оп,мм}} = 54,3$ $P_{\text{н,мм}} = 243,2$ $P_{\text{вн,мм}} = 69,1$ Гр. сл. = V Точн. = Н
	3К-122		3К-127
	$F, \text{ см}^2 = 5,313$ $Q, \text{ кг} = 1,440$ $D_{\text{оп,мм}} = 48,3$ $P_{\text{н,мм}} = 151,7$ $P_{\text{вн,мм}} = 127,9$ Гр. сл. = II Точн. = П		$F, \text{ см}^2 = 9,502$ $Q, \text{ кг} = 2,575$ $D_{\text{оп,мм}} = 82$ $P_{\text{н,мм}} = 615$ $P_{\text{вн,мм}} = 188$ Гр. сл. = □С Точн. = Н
	3К-123		3К-128
	$F, \text{ см}^2 = 2,624$ $Q, \text{ кг} = 0,711$ $D_{\text{оп,мм}} = 47,1$ $P_{\text{н,мм}} = 176,7$ $P_{\text{вн,мм}} = 33,2$ Гр. сл. = V I Точн. = П		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп,мм}} = -$ $P_{\text{н,мм}} = -$ $P_{\text{вн,мм}} = -$ Гр. сл. = - Точн. = -
	3К-124		3К-129
	$F, \text{ см}^2 = 97,568$ $Q, \text{ кг} = 26,441$ $D_{\text{оп,мм}} = 175,7$ $P_{\text{н,мм}} = 536,5$ $P_{\text{вн,мм}} = 366,2$ Гр. сл. = ОСБ Точн. = Н		$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп,мм}} =$ $P_{\text{н,мм}} =$ $P_{\text{вн,мм}} =$ Гр. сл. = ОС. Точн. = П
	3К-125		3К-130
	$F, \text{ см}^2 = 13,523$ $Q, \text{ кг} = 3,665$ $D_{\text{оп,мм}} = 94,3$ $P_{\text{н,мм}} = 245,1$ $P_{\text{вн,мм}} = 251$ Гр. сл. = ОСБ Точн. = П		$F, \text{ см}^2 = 4,843$ $Q, \text{ кг} = 1,312$ $D_{\text{оп,мм}} = 51$ $P_{\text{н,мм}} = 235,2$ $P_{\text{вн,мм}} = 71,5$ Гр. сл. = V I Точн. = Н











	ЗН-1	(П39.022)	ЗН-6
	$F \text{ см}^2 = 0.542$ $Q \text{ кг} = 0.147$ $D \text{ оп.мм} = 13$ $P \text{ н.мм} = 40.84$ $P \text{ в.мм} = 31.42$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 2.092$ $Q \text{ кг} = 0.567$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 136.9$ $P \text{ в.мм} = 56.6$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$
(ЛА-240)	ЗН-2	(П39.029)	ЗН-7
	$F \text{ см}^2 = 2.24$ $Q \text{ кг} = 0.607$ $D \text{ оп.мм} = 44.4$ $P \text{ н.мм} = 119.2$ $P \text{ в.мм} = 104$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F \text{ см}^2 = 1.71$ $Q \text{ кг} = 0.463$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 62.83$ $P \text{ в.мм} = 42.41$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = П$
(ЭЛ-01)	ЗН-3	(П39.034)	ЗН-8
	$F \text{ см}^2 = 1.72$ $Q \text{ кг} = 0.466$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 119.4$ $P \text{ в.мм} = 110$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F \text{ см}^2 = 3.52$ $Q \text{ кг} = 0.954$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 100.5$ $P \text{ в.мм} = 75.4$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = Н$
(П39.019)	ЗН-4	(П39.044)	ЗН-9
	$F \text{ см}^2 = 4.3$ $Q \text{ кг} = 1.17$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 182$ $P \text{ в.мм} = 162$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = Н$		$F \text{ см}^2 = 0.82$ $Q \text{ кг} = 0.223$ $D \text{ оп.мм} = 15$ $P \text{ н.мм} = 47.12$ $P \text{ в.мм} = 34.56$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$
(П39.020)	ЗН-5	(П39.049)	ЗН-10
	$F \text{ см}^2 = 9.41$ $Q \text{ кг} = 2.55$ $D \text{ оп.мм} = 128.2$ $P \text{ н.мм} = 415$ $P \text{ в.мм} = 344$ $\Gamma \text{р. сл.} = VII$ $\text{Точн.} = Н$		$F \text{ см}^2 = 17.01$ $Q \text{ кг} = 4.54$ $D \text{ оп.мм} = 107$ $P \text{ н.мм} = 364.7$ $P \text{ в.мм} = 251.33$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$











(П39.055)	ЗН-11	(П39.068)	ЗН-16
	$F \text{ см}^2 = 26.1$ $Q \text{ кг} = 7.021$ $D \text{ оп.мм} = 96$ $P \text{ н.мм} = 1754$ $P \text{ в.мм} = 157.1$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 5.56$ $Q \text{ кг} = 1.507$ $D \text{ оп.мм} = 62$ $P \text{ н.мм} = 194.8$ $P \text{ в.мм} = 175.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
(П39.056)	ЗН-12	(П39.005)	ЗН-17
	$F \text{ см}^2 = 32.65$ $Q \text{ кг} = 8.783$ $D \text{ оп.мм} = 96$ $P \text{ н.мм} = 1348$ $P \text{ в.мм} = 132$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3.57$ $Q \text{ кг} = 0.97$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 268.6$ $P \text{ в.мм} = 116$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$
(П39.060)	ЗН-13	(П39.006)	ЗН-18
	$F \text{ см}^2 = 1.41$ $Q \text{ кг} = 0.382$ $D \text{ оп.мм} = 18$ $P \text{ н.мм} = 56.55$ $P \text{ в.мм} = 37.7$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4.027$ $Q \text{ кг} = 1.092$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 263.2$ $P \text{ в.мм} = 140.1$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$
(П39.064)	ЗН-14	(П39.008)	ЗН-19
	$F \text{ см}^2 = 5.44$ $Q \text{ кг} = 1.47$ $D \text{ оп.мм} = 37$ $P \text{ н.мм} = 116.2$ $P \text{ в.мм} = 81.68$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4.444$ $Q \text{ кг} = 1.204$ $D \text{ оп.мм} = 57.5$ $P \text{ н.мм} = 166.3$ $P \text{ в.мм} = 37.7$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$
(П39.067)	ЗН-15	(П39.009)	ЗН-20
	$F \text{ см}^2 = 1.29$ $Q \text{ кг} = 0.35$ $D \text{ оп.мм} = 20.5$ $P \text{ н.мм} = 64.4$ $P \text{ в.мм} = 50.27$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3.66$ $Q \text{ кг} = 0.992$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 113.89$ $P \text{ в.мм} = 22.93$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$











(П39.013)	3Н-21	(П39.004)	3Н-26
	$F \text{ см}^2 = 3,584$ $Q \text{ кг} = 0,971$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 263,6$ $P \text{ в.мм} = 116$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3,849$ $Q \text{ кг} = 1,043$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 268,6$ $P \text{ в.мм} = 132$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
(П39.064-01)	3Н-22	(П39.012)	3Н-27
	$F \text{ см}^2 = 6,64$ $Q \text{ кг} = 1,799$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 122,5$ $P \text{ в.мм} = 81,68$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3,54$ $Q \text{ кг} = 0,96$ $D \text{ оп.мм} = 66,6$ $P \text{ н.мм} = 255,6$ $P \text{ в.мм} = 116$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
(П39.001)	3Н-23		3Н-28
	$F \text{ см}^2 = 3,079$ $Q \text{ кг} = 0,8344$ $D \text{ оп.мм} = 55,5$ $P \text{ н.мм} = 221,6$ $P \text{ в.мм} = 108$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 6,472$ $Q \text{ кг} = 1,754$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 122,5$ $P \text{ в.мм} = 82,9$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{H}$
(П39.002)	3Н-24		3Н-29
	$F \text{ см}^2 = 3,354$ $Q \text{ кг} = 0,909$ $D \text{ оп.мм} = 55,5$ $P \text{ н.мм} = 221,6$ $P \text{ в.мм} = 124$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3,02$ $Q \text{ кг} = 0,82$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 88$ $P \text{ в.мм} = 62,8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
(П39.003)	3Н-25		3Н-30
	$F \text{ см}^2 = 6,347$ $Q \text{ кг} = 1,72$ $D \text{ оп.мм} = 121$ $P \text{ н.мм} = 379,3$ $P \text{ в.мм} = 256,1$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 1,382$ $Q \text{ кг} = 0,375$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 75,4$ $P \text{ в.мм} = 62,8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$























	<p>ЗН-31</p>		<p>ЗН-36</p>
<p> <math>F \text{ см}^2 = 1.34</math>  <math>Q \text{ кг} = 0.375</math>  <math>D \text{ оп.мм} = 30</math>  <math>P \text{ н.мм} = 94.3</math>  <math>P \text{ в.мм} = 84.8</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = H</math> </p>		<p> <math>F \text{ см}^2 = 0.88</math>  <math>Q \text{ кг} = 0.239</math>  <math>D \text{ оп.мм} = 16</math>  <math>P \text{ н.мм} = 50.3</math>  <math>P \text{ в.мм} = 37.7</math>  <math>\Gamma \text{р. сл.} = IV</math>  <math>\text{Точн.} = H</math> </p>	
	<p>ЗН-32</p>		<p>ЗН-37</p>
<p> <math>F \text{ см}^2 = 2.388</math>  <math>Q \text{ кг} = 0.6472</math>  <math>D \text{ оп.мм} = 40</math>  <math>P \text{ н.мм} = 125.7</math>  <math>P \text{ в.мм} = 113.1</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = H</math> </p>		<p> <math>F \text{ см}^2 = 1.225</math>  <math>Q \text{ кг} = 0.332</math>  <math>D \text{ оп.мм} = 16</math>  <math>P \text{ н.мм} = 50.3</math>  <math>P \text{ в.мм} = 31.4</math>  <math>\Gamma \text{р. сл.} = IV</math>  <math>\text{Точн.} = H</math> </p>	
	<p>ЗН-33</p>		<p>ЗН-38</p>
<p> <math>F \text{ см}^2 = 3.64</math>  <math>Q \text{ кг} = 0.986</math>  <math>D \text{ оп.мм} = 43</math>  <math>P \text{ н.мм} = 111.6</math>  <math>P \text{ в.мм} = 105.6</math>  <math>\Gamma \text{р. сл.} = VII</math>  <math>\text{Точн.} = П</math> </p>		<p> <math>F \text{ см}^2 = 0.495</math>  <math>Q \text{ кг} = 0.134</math>  <math>D \text{ оп.мм} = 12</math>  <math>P \text{ н.мм} = 37.7</math>  <math>P \text{ в.мм} = 28.27</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = H</math> </p>	
	<p>ЗН-34</p>		<p>ЗН-39</p>
<p> <math>F, \text{ см}^2 = 54.336</math>  <math>Q, \text{ кг} = 14.725</math>  <math>D \text{ оп.мм} = 116</math>  <math>P \text{ н.мм} = 388.6</math>  <math>P \text{ в.мм} = 182.1</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = H</math> </p>		<p> <math>F \text{ см}^2 = 0.746</math>  <math>Q \text{ кг} = 0.2022</math>  <math>D \text{ оп.мм} = 12</math>  <math>P \text{ н.мм} = 37.7</math>  <math>P \text{ в.мм} = 21.99</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = H</math> </p>	
	<p>ЗН-35</p>		<p>ЗН-40</p>
<p> <math>F \text{ см}^2 = 15.2</math>  <math>Q \text{ кг} = 4.12</math>  <math>D \text{ оп.мм} = 58</math>  <math>P \text{ н.мм} = 179.4</math>  <math>P \text{ в.мм} = 110</math>  <math>\Gamma \text{р. сл.} = III</math>  <math>\text{Точн.} = H</math> </p>		<p> <math>F \text{ см}^2 = 10.272</math>  <math>Q \text{ кг} = 2.783</math>  <math>D \text{ оп.мм} = 113.4</math>  <math>P \text{ н.мм} = 659.9</math>  <math>P \text{ в.мм} = 259.8</math>  <math>\Gamma \text{р. сл.} = VII</math>  <math>\text{Точн.} = П</math> </p>	











	ЗН-41 $F \text{ см}^2 = 2,29$ $Q \text{ кг} = 0,621$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 147,7$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$		ЗН-46 $F \text{ см}^2 = 10,556$ $Q \text{ кг} = 2,85$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 106,8$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$
	ЗН-42 $F \text{ см}^2 = 2,433$ $Q \text{ кг} = 0,659$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 147$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$		ЗН-47 $F \text{ см}^2 = 0,589$ $Q \text{ кг} = 0,16$ $D \text{ оп.мм} = 14$ $P \text{ н.мм} = 44$ $P \text{ в.мм} = 34,6$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$
	ЗН-43 $F \text{ см}^2 = 3,016$ $Q \text{ кг} = 0,818$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 144,5$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$		ЗН-48 $F \text{ см}^2 = 4,123$ $Q \text{ кг} = 1,117$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78,54$ $P \text{ в.мм} = 31,4$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$
	ЗН-44 $F \text{ см}^2 = 3,731$ $Q \text{ кг} = 1,011$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 141,4$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$		ЗН-49 $F \text{ см}^2 = 2,77$ $Q \text{ кг} = 0,751$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78,54$ $P \text{ в.мм} = 51,84$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$
	ЗН-45 $F \text{ см}^2 = 4,43$ $Q \text{ кг} = 1,2$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 138,2$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$		ЗН-50 $F \text{ см}^2 = 3,61$ $Q \text{ кг} = 0,978$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 87,96$ $P \text{ в.мм} = 56,55$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$

	3Н-51		3Н-56
	$F \text{ см}^2 = 2.1$ $Q \text{ кг} = 0.569$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 62.8$ $P \text{ в.мм} = 36.1$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 4.742$ $Q \text{ кг} = 1.285$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 100.5$ $P \text{ в.мм} = 64.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-52		3Н-57
	$F \text{ см}^2 = 2.262$ $Q \text{ кг} = 0.613$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 69.12$ $P \text{ в.мм} = 44$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 5.78$ $Q \text{ кг} = 1.566$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 106.8$ $P \text{ в.мм} = 64.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-53		3Н-58
	$F \text{ см}^2 = 1.131$ $Q \text{ кг} = 0.307$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 62.83$ $P \text{ в.мм} = 50.27$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 4.273$ $Q \text{ кг} = 1.16$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78.54$ $P \text{ в.мм} = 28.27$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-54		3Н-59
	$F \text{ см}^2 = 1.257$ $Q \text{ кг} = 0.341$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 69.12$ $P \text{ в.мм} = 56.55$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 5.655$ $Q \text{ кг} = 1.532$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 113.1$ $P \text{ в.мм} = 75.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-55		3Н-60
	$F \text{ см}^2 = 1.154$ $Q \text{ кг} = 0.313$ $D \text{ оп.мм} = 14$ $P \text{ н.мм} = 44$ $P \text{ в.мм} = 23$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 5.94$ $Q \text{ кг} = 1.61$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 106.8$ $P \text{ в.мм} = 62.8$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$

	<p>ЗН-61</p> <p> <math>F \text{ см}^2 = 4,9</math>  <math>Q \text{ кг} = 1,328</math>  <math>D \text{ оп.мм} = 32</math>  <math>P \text{ н.мм} = 100,5</math>  <math>P \text{ в.мм} = 62,8</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{Н}</math> </p>		<p>ЗН-66</p> <p> <math>F \text{ см}^2 = 88</math>  <math>Q \text{ кг} = 2,385</math>  <math>D \text{ оп.мм} = 38</math>  <math>P \text{ н.мм} = 119,4</math>  <math>P \text{ в.мм} = 56,6</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{Н}</math> </p>
	<p>ЗН-62</p> <p> <math>F \text{ см}^2 = 3,14</math>  <math>Q \text{ кг} = 0,851</math>  <math>D \text{ оп.мм} = 25</math>  <math>P \text{ н.мм} = 78,54</math>  <math>P \text{ в.мм} = 47,12</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{Н}</math> </p>		<p>ЗН-67</p> <p> <math>F \text{ см}^2 = 10,33</math>  <math>Q \text{ кг} = 2,8</math>  <math>D \text{ оп.мм} = 47</math>  <math>P \text{ н.мм} = 144,8</math>  <math>P \text{ в.мм} = 84,8</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{Н}</math> </p>
	<p>ЗН-63</p> <p> <math>F \text{ см}^2 = 2,948</math>  <math>Q \text{ кг} = 0,8</math>  <math>D \text{ оп.мм} = 44,2</math>  <math>P \text{ н.мм} = 117</math>  <math>P \text{ в.мм} = 112</math>  <math>\Gamma \text{ р. сл.} = \text{II}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p>ЗН-68</p> <p> <math>F \text{ см}^2 = 8,55</math>  <math>Q \text{ кг} = 2,32</math>  <math>D \text{ оп.мм} = 42</math>  <math>P \text{ н.мм} = 131,9</math>  <math>P \text{ в.мм} = 81,7</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{Н}</math> </p>
	<p>ЗН-64</p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ в.мм} =</math>  <math>\Gamma \text{ р. сл.} =</math>  <math>\text{Точн.} = \text{Н}</math> </p>		<p>ЗН-69</p> <p> <math>F \text{ см}^2 = 7,52</math>  <math>Q \text{ кг} = 2,038</math>  <math>D \text{ оп.мм} = 104</math>  <math>P \text{ н.мм} = 412,4</math>  <math>P \text{ в.мм} = 314,7</math>  <math>\Gamma \text{ р. сл.} = \text{VII}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p>ЗН-65</p> <p> <math>F \text{ см}^2 = 8,04</math>  <math>Q \text{ кг} = 2,18</math>  <math>D \text{ оп.мм} = 38</math>  <math>P \text{ н.мм} = 119,4</math>  <math>P \text{ в.мм} = 64,4</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{Н}</math> </p>		<p>ЗН-70</p> <p> <math>F \text{ см}^2 = 2,04</math>  <math>Q \text{ кг} = 0,553</math>  <math>D \text{ оп.мм} = 22</math>  <math>P \text{ н.мм} = 69,1</math>  <math>P \text{ в.мм} = 47,1</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{Н}</math> </p>










	<p>ЗН-71</p> <p> <math>F \text{ см}^2 = 10.05</math>  <math>Q \text{ кг} = 2.724</math>  <math>D \text{ оп.мм} = 42</math>  <math>P \text{ н.мм} = 131.9</math>  <math>P \text{ в.мм} = 69.1</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>		<p>ЗН-76</p> <p> <math>F \text{ см}^2 = 4.233</math>  <math>Q \text{ кг} = 1.147</math>  <math>D \text{ оп.мм} = 42</math>  <math>P \text{ н.мм} = 132</math>  <math>P \text{ в.мм} = 110</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>
	<p>ЗН-72</p> <p> <math>F \text{ см}^2 = 5.28</math>  <math>Q \text{ кг} = 1.431</math>  <math>D \text{ оп.мм} = 34</math>  <math>P \text{ н.мм} = 106.8</math>  <math>P \text{ в.мм} = 69.1</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>		<p>ЗН-77</p> <p> <math>F \text{ см}^2 = 3.3</math>  <math>Q \text{ кг} = 0.894</math>  <math>D \text{ оп.мм} = 37</math>  <math>P \text{ н.мм} = 116.2</math>  <math>P \text{ в.мм} = 96.7</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>
	<p>ЗН-73</p> <p> <math>F \text{ см}^2 = 6.03</math>  <math>Q \text{ кг} = 1.634</math>  <math>D \text{ оп.мм} = 38</math>  <math>P \text{ н.мм} = 119.4</math>  <math>P \text{ в.мм} = 81.7</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>		<p>ЗН-78</p> <p> <math>F \text{ см}^2 = 3.5</math>  <math>Q \text{ кг} = 0.95</math>  <math>D \text{ оп.мм} = 39</math>  <math>P \text{ н.мм} = 122.5</math>  <math>P \text{ в.мм} = 103</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>
	<p>ЗН-74</p> <p> <math>F \text{ см}^2 = 2.513</math>  <math>Q \text{ кг} = 0.681</math>  <math>D \text{ оп.мм} = 24</math>  <math>P \text{ н.мм} = 75.4</math>  <math>P \text{ в.мм} = 50.3</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>		<p>ЗН-79</p> <p> <math>F \text{ см}^2 = 2.4</math>  <math>Q \text{ кг} = 0.65</math>  <math>D \text{ оп.мм} = 32</math>  <math>P \text{ н.мм} = 100.5</math>  <math>P \text{ в.мм} = 84.2</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>
	<p>ЗН-75</p> <p> <math>F \text{ см}^2 = 2.015</math>  <math>Q \text{ кг} = 0.546</math>  <math>D \text{ оп.мм} = 20</math>  <math>P \text{ н.мм} = 75.4</math>  <math>P \text{ в.мм} = 50.3</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>		<p>ЗН-80</p> <p> <math>F \text{ см}^2 = 2.07</math>  <math>Q \text{ кг} = 0.561</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 88</math>  <math>P \text{ в.мм} = 71.6</math>  <math>\Gamma \text{ р. сл.} = \text{III}</math>  <math>\text{Точн.} = \text{H}</math> </p>









	3Н-81		3Н-86
	$F \text{ см}^2 = 1.56$ $Q \text{ кг} = 0.423$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 75.4$ $P \text{ в.мм} = 61$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2.168$ $Q, \text{ кг} = 0.587$ $D \text{ оп.мм} = 26$ $P \text{ н.мм} = 81.68$ $P \text{ в.мм} = 62.83$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-82		3Н-87
	$F \text{ см}^2 = 5.18$ $Q \text{ кг} = 1.404$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 94.25$ $P \text{ в.мм} = 48.69$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 2.63$ $Q \text{ кг} = 0.713$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 113.1$ $P \text{ в.мм} = 97.4$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-83		3Н-88
	$F \text{ см}^2 = 4.215$ $Q \text{ кг} = 1.142$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 29.53$ $P \text{ в.мм} = 78.54$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3.927$ $Q \text{ кг} = 1.064$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 94.25$ $P \text{ в.мм} = 62.83$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-84		3Н-89
	$F \text{ см}^2 = 2.254$ $Q \text{ кг} = 0.611$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 75.4$ $P \text{ в.мм} = 53.41$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 5.184$ $Q \text{ кг} = 1.405$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 119.4$ $P \text{ в.мм} = 87.96$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-85		3Н-90
	$F \text{ см}^2 = 10.23$ $Q \text{ кг} = 2.771$ $D \text{ оп.мм} = 53.5$ $P \text{ н.мм} = 168.1$ $P \text{ в.мм} = 124.1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3.322$ $Q \text{ кг} = 0.9$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 87.96$ $P \text{ в.мм} = 59.69$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$











	ЗН-91		ЗН-96
	$F, \text{ см}^2 = 3.888$ $Q, \text{ кг} = 1.053$ $D_{\text{оп.мм}} = 28$ $P_{\text{н.мм}} = 87.96$ $P_{\text{вн.мм}} = 53.41$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 9.29$ $Q, \text{ кг} = 2.518$ $D_{\text{оп.мм}} = 52$ $P_{\text{н.мм}} = 163.4$ $P_{\text{вн.мм}} = 122.5$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-92		ЗН-97
	$F, \text{ см}^2 = 3.605$ $Q, \text{ кг} = 0.977$ $D_{\text{оп.мм}} = 30$ $P_{\text{н.мм}} = 94.25$ $P_{\text{вн.мм}} = 65.97$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.529$ $Q, \text{ кг} = 1.498$ $D_{\text{оп.мм}} = 90$ $P_{\text{н.мм}} = 282.7$ $P_{\text{вн.мм}} = 270.2$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-93		ЗН-98
	$F, \text{ см}^2 = 6.48$ $Q, \text{ кг} = 1.756$ $D_{\text{оп.мм}} = 35$ $P_{\text{н.мм}} = 109.95$ $P_{\text{вн.мм}} = 62.83$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2.073$ $Q, \text{ кг} = 0.562$ $D_{\text{оп.мм}} = 35$ $P_{\text{н.мм}} = 110$ $P_{\text{вн.мм}} = 97.4$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-94		ЗН-99
	$F, \text{ см}^2 = 0.903$ $Q, \text{ кг} = 0.245$ $D_{\text{оп.мм}} = 14$ $P_{\text{н.мм}} = 47.98$ $P_{\text{вн.мм}} = 28.27$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 0.858$ $Q, \text{ кг} = 0.233$ $D_{\text{оп.мм}} = 12$ $P_{\text{н.мм}} = 37.7$ $P_{\text{вн.мм}} = 18.85$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-95		ЗН-100
	$F, \text{ см}^2 = 1.532$ $Q, \text{ кг} = 0.415$ $D_{\text{оп.мм}} = 22$ $P_{\text{н.мм}} = 69.12$ $P_{\text{вн.мм}} = 53.41$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4.87$ $Q, \text{ кг} = 1.32$ $D_{\text{оп.мм}} = 36$ $P_{\text{н.мм}} = 113.1$ $P_{\text{вн.мм}} = 81.68$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$











	ЗН-101		ЗН-106
	$F, \text{ см}^2 = 6.715$ $Q, \text{ кг} = 1.82$ $D_{\text{оп, мм}} = 32$ $P_{\text{н, мм}} = 100.5$ $P_{\text{вн, мм}} = 40.8$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 5.867$ $Q, \text{ кг} = 1.59$ $D_{\text{оп, мм}} = 38$ $P_{\text{н, мм}} = 119.4$ $P_{\text{вн, мм}} = 82.9$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{Н}$
	ЗН-102		ЗН-107
	$F, \text{ см}^2 = 4.273$ $Q, \text{ кг} = 1.158$ $D_{\text{оп, мм}} = 38$ $P_{\text{н, мм}} = 119.4$ $P_{\text{вн, мм}} = 94.25$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 5.374$ $Q, \text{ кг} = 1.456$ $D_{\text{оп, мм}} = 83.65$ $P_{\text{н, мм}} = 379.3$ $P_{\text{вн, мм}} = 110.8$ $\Gamma_{\text{р. сл.}} = \text{ОС.}$ $\text{Точн.} = \text{Н}$
	ЗН-103		ЗН-108
	$F, \text{ см}^2 = 48.95$ $Q, \text{ кг} = 13.51$ $D_{\text{оп, мм}} = 112$ $P_{\text{н, мм}} = 377.8$ $P_{\text{вн, мм}} = 182.3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$		$F, \text{ см}^2 = 1.602$ $Q, \text{ кг} = 0.434$ $D_{\text{оп, мм}} = 20$ $P_{\text{н, мм}} = 62.83$ $P_{\text{вн, мм}} = 43.98$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	ЗН-104		ЗН-109
	$F, \text{ см}^2 = 1.814$ $Q, \text{ кг} = 0.492$ $D_{\text{оп, мм}} = 20$ $P_{\text{н, мм}} = 62.8$ $P_{\text{вн, мм}} = 40.8$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 6.296$ $Q, \text{ кг} = 1.706$ $D_{\text{оп, мм}} = 95.83$ $P_{\text{н, мм}} = 373.9$ $P_{\text{вн, мм}} = 223.1$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$
	ЗН-105		ЗН-110
	$F, \text{ см}^2 = 2.724$ $Q, \text{ кг} = 0.738$ $D_{\text{оп, мм}} = 64$ $P_{\text{н, мм}} = 152.2$ $P_{\text{вн, мм}} = 317.7$ $\Gamma_{\text{р. сл.}} = \text{ОС.}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 9.766$ $Q, \text{ кг} = 2.647$ $D_{\text{оп, мм}} = 114$ $P_{\text{н, мм}} = 578$ $P_{\text{вн, мм}} = 294.2$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$























	ЗН-111		ЗН-116
	$F, \text{ см}^2 = 4.318$ $Q, \text{ кг} = 1.17$ $D_{\text{оп, мм}} = 66.3$ $P_{\text{н, мм}} = 257.2$ $P_{\text{вн, мм}} = 154.87$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 1.759$ $Q, \text{ кг} = 0.477$ $D_{\text{оп, мм}} = 30$ $P_{\text{н, мм}} = 94.3$ $P_{\text{вн, мм}} = 81.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-112		ЗН-117
	$F, \text{ см}^2 = 6.841$ $Q, \text{ кг} = 1.854$ $D_{\text{оп, мм}} = 40$ $P_{\text{н, мм}} = 126$ $P_{\text{вн, мм}} = 85$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп, мм}} = -$ $P_{\text{н, мм}} = -$ $P_{\text{вн, мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	ЗН-113		ЗН-118
	$F, \text{ см}^2 = 13.95$ $Q, \text{ кг} = 3.78$ $D_{\text{оп, мм}} = 80$ $P_{\text{н, мм}} = 251.3$ $P_{\text{вн, мм}} = 213.6$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 3.3$ $Q, \text{ кг} = 0.894$ $D_{\text{оп, мм}} = 55$ $P_{\text{н, мм}} = 162.3$ $P_{\text{вн, мм}} = 104.9$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$
	ЗН-114		ЗН-119
	$F, \text{ см}^2 = 7.257$ $Q, \text{ кг} = 1.967$ $D_{\text{оп, мм}} = 40$ $P_{\text{н, мм}} = 125.7$ $P_{\text{вн, мм}} = 81.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 1.013$ $Q, \text{ кг} = 0.274$ $D_{\text{оп, мм}} = 15$ $P_{\text{н, мм}} = 47.1$ $P_{\text{вн, мм}} = 30.8$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-115		ЗН-120
	$F, \text{ см}^2 = 2.478$ $Q, \text{ кг} = 0.672$ $D_{\text{оп, мм}} = 30.1$ $P_{\text{н, мм}} = 94.6$ $P_{\text{вн, мм}} = 76.3$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4.799$ $Q, \text{ кг} = 1.3$ $D_{\text{оп, мм}} = 30$ $P_{\text{н, мм}} = 94.2$ $P_{\text{вн, мм}} = 53.4$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$










	<p><b>ПЗ-01</b></p> <p> <math>F \text{ см}^2 = 6.540</math>  <math>Q \text{ кг.} = 1.772</math>  <math>D \text{ оп.мм} = 139.0</math>  <math>P \text{ н.мм} = 309.8</math>  <math>P \text{ вн.мм} = 337.8</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>ПЗ-06</b></p> <p> <math>F \text{ см}^2 = 2.548</math>  <math>Q \text{ кг.} = 0.691</math>  <math>D \text{ оп.мм} = 53.5</math>  <math>P \text{ н.мм} = 235.0</math>  <math>P \text{ вн.мм} = 134.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-02</b></p> <p> <math>F \text{ см}^2 = 3.506</math>  <math>Q \text{ кг.} = 0.950</math>  <math>D \text{ оп.мм} = 67.0</math>  <math>P \text{ н.мм} = 243.0</math>  <math>P \text{ вн.мм} = 106.5</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>ПЗ-7</b></p> <p> <math>F \text{ см}^2 = 0.952</math>  <math>Q \text{ кг.} = 0.258</math>  <math>D \text{ оп.мм} = 32.0</math>  <math>P \text{ н.мм} = 120.5</math>  <math>P \text{ вн.мм} = 36.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-03</b></p> <p> <math>F \text{ см}^2 = 1.324</math>  <math>Q \text{ кг.} = 0.359</math>  <math>D \text{ оп.мм} = 31.8</math>  <math>P \text{ н.мм} = 112.2</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>ПЗ-08</b></p> <p> <math>F \text{ см}^2 = 4.200</math>  <math>Q \text{ кг.} = 1.138</math>  <math>D \text{ оп.мм} = 90.0</math>  <math>P \text{ н.мм} = 342.3</math>  <math>P \text{ вн.мм} = 114.4</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-04</b></p> <p> <math>F \text{ см}^2 = 3.060</math>  <math>Q \text{ кг.} = 0.829</math>  <math>D \text{ оп.мм} = 54.0</math>  <math>P \text{ н.мм} = 135.7</math>  <math>P \text{ вн.мм} = 120.8</math>  Гр. сл. = V  Точн. = П </p>		
			<p><b>ПЗ-10</b></p> <p> <math>F \text{ см}^2 = 1.800</math>  <math>Q \text{ кг.} = 0.488</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 165.0</math>  <math>P \text{ вн.мм} = 75.0</math>  Гр. сл. = VI  Точн. = П </p>










	<p><b>ПЗ-11</b></p> <p> <math>F \text{ см}^2 = 2.335</math>  <math>Q \text{ кг.} = 0.633</math>  <math>D \text{ оп.мм} = 56.0</math>  <math>P \text{ н.мм} = 221.2</math>  <math>P \text{ вн.мм} = 132.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-16</b></p> <p> <math>F \text{ см}^2 = 2.544</math>  <math>Q \text{ кг.} = 0.689</math>  <math>D \text{ оп.мм} = 42.4</math>  <math>P \text{ н.мм} = 182.3</math>  <math>P \text{ вн.мм} = 57.1</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-12</b></p> <p> <math>F \text{ см}^2 = 1.313</math>  <math>Q \text{ кг.} = 0.356</math>  <math>D \text{ оп.мм} = 32.0</math>  <math>P \text{ н.мм} = 132.0</math>  <math>P \text{ вн.мм} = 67.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-17</b></p> <p> <math>F \text{ см}^2 = 2.695</math>  <math>Q \text{ кг.} = 0.730</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 200.9</math>  <math>P \text{ вн.мм} = 57.1</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>ПЗ-13</b></p> <p> <math>F \text{ см}^2 = 5.190</math>  <math>Q \text{ кг.} = 1.406</math>  <math>D \text{ оп.мм} = 84.1</math>  <math>P \text{ н.мм} = 321.6</math>  <math>P \text{ вн.мм} = 124.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>ПЗ-18</b></p> <p> <math>F \text{ см}^2 = 3.014</math>  <math>Q \text{ кг.} = 0.817</math>  <math>D \text{ оп.мм} = 46.8</math>  <math>P \text{ н.мм} = 172.3</math>  <math>P \text{ вн.мм} = 129.1</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-15</b></p> <p> <math>F \text{ см}^2 = 1.927</math>  <math>Q \text{ кг.} = 0.522</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 178.4</math>  <math>P \text{ вн.мм} = 78.6</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-19</b></p> <p> <math>F \text{ см}^2 = 2.926</math>  <math>Q \text{ кг.} = 0.793</math>  <math>D \text{ оп.мм} = 46.1</math>  <math>P \text{ н.мм} = 217.5</math>  <math>P \text{ вн.мм} = 57.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>ПЗ-20</b></p> <p> <math>F \text{ см}^2 = 2.919</math>  <math>Q \text{ кг.} = 0.791</math>  <math>D \text{ оп.мм} = 46.0</math>  <math>P \text{ н.мм} = 219.2</math>  <math>P \text{ вн.мм} = 55.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-20</b></p> <p> <math>F \text{ см}^2 = 2.919</math>  <math>Q \text{ кг.} = 0.791</math>  <math>D \text{ оп.мм} = 46.0</math>  <math>P \text{ н.мм} = 219.2</math>  <math>P \text{ вн.мм} = 55.0</math>  Гр. сл. = V  Точн. = П </p>

	<p><b>ПЗ-21</b></p> <p> <math>F \text{ см}^2 = 2.779</math>  <math>Q \text{ кг.} = 0.753</math>  <math>D \text{ оп.мм} = 47.0</math>  <math>P \text{ н.мм} = 177.3</math>  <math>P \text{ вн.мм} = 93.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-26</b></p> <p> <math>F \text{ см}^2 = 2.650</math>  <math>Q \text{ кг.} = 0.718</math>  <math>D \text{ оп.мм} = 100.0</math>  <math>P \text{ н.мм} = 229.6</math>  <math>P \text{ вн.мм} = 45.2</math>  Гр. сл. = V  Точн. = Н </p>
	<p><b>ПЗ-22</b></p> <p> <math>F \text{ см}^2 = 2.065</math>  <math>Q \text{ кг.} = 0.560</math>  <math>D \text{ оп.мм} = 36.0</math>  <math>P \text{ н.мм} = 135.0</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-27</b></p> <p> <math>F \text{ см}^2 = 3.290</math>  <math>Q \text{ кг.} = 0.892</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 250.0</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-23</b></p> <p> <math>F \text{ см}^2 = 2.665</math>  <math>Q \text{ кг.} = 0.722</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 195.0</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-28</b></p> <p> <math>F \text{ см}^2 = 6.245</math>  <math>Q \text{ кг.} = 1.692</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 387.0</math>  <math>P \text{ вн.мм} = 192.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>ПЗ-24</b></p> <p> <math>F \text{ см}^2 = 2.690</math>  <math>Q \text{ кг.} = 0.729</math>  <math>D \text{ оп.мм} = 46.0</math>  <math>P \text{ н.мм} = 190.0</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-29</b></p> <p> <math>F \text{ см}^2 = 7.720</math>  <math>Q \text{ кг.} = 2.092</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 512.0</math>  <math>P \text{ вн.мм} = 192.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>ПЗ-25</b></p> <p> <math>F \text{ см}^2 = 2.365</math>  <math>Q \text{ кг.} = 0.641</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 165.0</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-30</b></p> <p> <math>F \text{ см}^2 = 2.990</math>  <math>Q \text{ кг.} = 0.810</math>  <math>D \text{ оп.мм} = 48.0</math>  <math>P \text{ н.мм} = 220.0</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = V  Точн. = П </p>










	<p><b>ПЗ-31</b></p> <p> <math>F \text{ см}^2 = 2.840</math>  <math>Q \text{ кг.} = 0.770</math>  <math>D \text{ оп.мм} = 42.4</math>  <math>P \text{ н.мм} = 208.6</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-36</b></p> <p> <math>F \text{ см}^2 = 2.340</math>  <math>Q \text{ кг.} = 0.634</math>  <math>D \text{ оп.мм} = 38.8</math>  <math>P \text{ н.мм} = 154.6</math>  <math>P \text{ вн.мм} = 15.7</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-32</b></p> <p> <math>F \text{ см}^2 = 5.990</math>  <math>Q \text{ кг.} = 1.623</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 389.6</math>  <math>P \text{ вн.мм} = 96.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-37</b></p> <p> <math>F \text{ см}^2 = 1.324</math>  <math>Q \text{ кг.} = 0.359</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 97.0</math>  <math>P \text{ вн.мм} = 15.7</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-33</b></p> <p> <math>F \text{ см}^2 = 4.533</math>  <math>Q \text{ кг.} = 1.228</math>  <math>D \text{ оп.мм} = 49.0</math>  <math>P \text{ н.мм} = 376.3</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-38</b></p> <p> <math>F \text{ см}^2 = 3.427</math>  <math>Q \text{ кг.} = 0.928</math>  <math>D \text{ оп.мм} = 49.0</math>  <math>P \text{ н.мм} = 258.2</math>  <math>P \text{ вн.мм} = 69.26</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-34</b></p> <p> <math>F \text{ см}^2 = 3.616</math>  <math>Q \text{ кг.} = 0.980</math>  <math>D \text{ оп.мм} = 46.7</math>  <math>P \text{ н.мм} = 282.3</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-39</b></p> <p> <math>F \text{ см}^2 = 3.712</math>  <math>Q \text{ кг.} = 1.006</math>  <math>D \text{ оп.мм} = 67.0</math>  <math>P \text{ н.мм} = 314.6</math>  <math>P \text{ вн.мм} = 66.4</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-35</b></p> <p> <math>F \text{ см}^2 = 4.770</math>  <math>Q \text{ кг.} = 1.293</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 262.0</math>  <math>P \text{ вн.мм} = 192.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-40</b></p> <p> <math>F \text{ см}^2 = 8.740</math>  <math>Q \text{ кг.} = 2.369</math>  <math>D \text{ оп.мм} = 190.0</math>  <math>P \text{ н.мм} = 581.7</math>  <math>P \text{ вн.мм} = 245.3</math>  Гр. сл. = 0соб.  Точн. = П </p>











	<p><b>ПЗ-41</b></p> <p> <math>F \text{ см}^2 = 7.446</math>  <math>Q \text{ кг.} = 2.018</math>  <math>D \text{ оп.мм} = 168.0</math>  <math>P \text{ н.мм} = 502.1</math>  <math>P \text{ вн.мм} = 227.4</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-46</b></p> <p> <math>F \text{ см}^2 = 2.289</math>  <math>Q \text{ кг.} = 0.620</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 204.0</math>  <math>P \text{ вн.мм} = 134.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-42</b></p> <p> <math>F \text{ см}^2 = 2.557</math>  <math>Q \text{ кг.} = 0.693</math>  <math>D \text{ оп.мм} = 38.8</math>  <math>P \text{ н.мм} = 156.3</math>  <math>P \text{ вн.мм} = 40.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-47</b></p> <p> <math>F \text{ см}^2 = 1.324</math>  <math>Q \text{ кг.} = 0.359</math>  <math>D \text{ оп.мм} = 31.0</math>  <math>P \text{ н.мм} = 120.0</math>  <math>P \text{ вн.мм} = 72.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-43</b></p> <p> <math>F \text{ см}^2 = 1.340</math>  <math>Q \text{ кг.} = 0.363</math>  <math>D \text{ оп.мм} = 31.0</math>  <math>P \text{ н.мм} = 72.5</math>  <math>P \text{ вн.мм} = 18.9</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>ПЗ-48</b></p> <p> <math>F \text{ см}^2 = 1.813</math>  <math>Q \text{ кг.} = 0.518</math>  <math>D \text{ оп.мм} = 46</math>  <math>P \text{ н.мм} = 151</math>  <math>P \text{ вн.мм} = 134</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-44</b></p> <p> <math>F \text{ см}^2 = 1.430</math>  <math>Q \text{ кг.} = 0.388</math>  <math>D \text{ оп.мм} = 31.0</math>  <math>P \text{ н.мм} = 75.0</math>  <math>P \text{ вн.мм} = 18.9</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>ПЗ-49</b></p> <p> <math>F \text{ см}^2 = 7.025</math>  <math>Q \text{ кг.} = 1.904</math>  <math>D \text{ оп.мм} = 111.6</math>  <math>P \text{ н.мм} = 422.8</math>  <math>P \text{ вн.мм} = 184.5</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-45</b></p> <p> <math>F \text{ см}^2 = 4.900</math>  <math>Q \text{ кг.} = 1.328</math>  <math>D \text{ оп.мм} = 85.5</math>  <math>P \text{ н.мм} = 330.1</math>  <math>P \text{ вн.мм} = 188.3</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>ПЗ-50</b></p> <p> <math>F \text{ см}^2 = 9.457</math>  <math>Q \text{ кг.} = 2.563</math>  <math>D \text{ оп.мм} = 135.5</math>  <math>P \text{ н.мм} = 522.8</math>  <math>P \text{ вн.мм} = 284.9</math>  Гр. сл. = V  Точн. = П </p>











	<p><b>ПЗ-51</b></p> <p> <math>F \text{ см}^2 = 9.285</math>  <math>Q \text{ кг.} = 2.516</math>  <math>D \text{ оп.мм} = 97.1</math>  <math>P \text{ н.мм} = 647.6</math>  <math>P \text{ вн.мм} = 188.5</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-56</b></p> <p> <math>F \text{ см}^2 = 0.823</math>  <math>Q \text{ кг.} = 0.223</math>  <math>D \text{ оп.мм} = 23.3</math>  <math>P \text{ н.мм} = 93.2</math>  <math>P \text{ вн.мм} = 34.5</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-52</b></p> <p> <math>F \text{ см}^2 = 4.083</math>  <math>Q \text{ кг.} = 1.106</math>  <math>D \text{ оп.мм} = 57.8</math>  <math>P \text{ н.мм} = 257.4</math>  <math>P \text{ вн.мм} = 133.4</math>  Гр. сл. = V  Точн. = П </p>		
	<p><b>ПЗ-53</b></p> <p> <math>F \text{ см}^2 = 6.023</math>  <math>Q \text{ кг.} = 1.632</math>  <math>D \text{ оп.мм} = 86.5</math>  <math>P \text{ н.мм} = 327.4</math>  <math>P \text{ вн.мм} = 206.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-58</b></p> <p> <math>F \text{ см}^2 = 2.663</math>  <math>Q \text{ кг.} = 0.722</math>  <math>D \text{ оп.мм} = 57.0</math>  <math>P \text{ н.мм} = 214.2</math>  <math>P \text{ вн.мм} = 134.7</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>ПЗ-54</b></p> <p> <math>F \text{ см}^2 = 7.309</math>  <math>Q \text{ кг.} = 1.981</math>  <math>D \text{ оп.мм} = 109.7</math>  <math>P \text{ н.мм} = 377.4</math>  <math>P \text{ вн.мм} = 253.5</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-59</b></p> <p> <math>F \text{ см}^2 = 2.982</math>  <math>Q \text{ кг.} = 0.808</math>  <math>D \text{ оп.мм} = 57.0</math>  <math>P \text{ н.мм} = 258.0</math>  <math>P \text{ вн.мм} = 142.0</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>ПЗ-55</b></p> <p> <math>F \text{ см}^2 = 3.758</math>  <math>Q \text{ кг.} = 1.018</math>  <math>D \text{ оп.мм} = 53.3</math>  <math>P \text{ н.мм} = 153.4</math>  <math>P \text{ вн.мм} = 168.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-60</b></p> <p> <math>F \text{ см}^2 = 3.300</math>  <math>Q \text{ кг.} = 0.894</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} = 157.8</math>  <math>P \text{ вн.мм} = 34.6</math>  Гр. сл. = IV  Точн. = П </p>











	<p><b>ПЗ-61</b></p> <p> <math>F \text{ см}^2 = 2.790</math>  <math>Q \text{ кг.} = 0.756</math>  <math>D \text{ оп.мм} = 64.0</math>  <math>P \text{ н.мм} = 228.2</math>  <math>P \text{ вн.мм} = 135.4</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-66</b></p> <p> <math>F \text{ см}^2 = 3.301</math>  <math>Q \text{ кг.} = 0.895</math>  <math>D \text{ оп.мм} = 69.0</math>  <math>P \text{ н.мм} = 255.6</math>  <math>P \text{ вн.мм} = 178.0</math>  Гр. сл. = IV  Точн. = П </p>
			<p><b>ПЗ-67</b></p> <p> <math>F \text{ см}^2 = 5.382</math>  <math>Q \text{ кг.} = 1.459</math>  <math>D \text{ оп.мм} = 126.0</math>  <math>P \text{ н.мм} = 418.0</math>  <math>P \text{ вн.мм} = 302.0</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>ПЗ-63</b></p> <p> <math>F \text{ см}^2 = 3.879</math>  <math>Q \text{ кг.} = 1.051</math>  <math>D \text{ оп.мм} = 55.5</math>  <math>P \text{ н.мм} = 215.8</math>  <math>P \text{ вн.мм} = 115.4</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-68</b></p> <p> <math>F \text{ см}^2 = 4.238</math>  <math>Q \text{ кг.} = 1.148</math>  <math>D \text{ оп.мм} = 68.0</math>  <math>P \text{ н.мм} = 294.9</math>  <math>P \text{ вн.мм} = 154.0</math>  Гр. сл. = V  Точн. = Н </p>
	<p><b>ПЗ-64</b></p> <p> <math>F \text{ см}^2 = 2.618</math>  <math>Q \text{ кг.} = 0.709</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>P \text{ н.мм} = 198.5</math>  <math>P \text{ вн.мм} = 62.4</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>ПЗ-69</b></p> <p> <math>F \text{ см}^2 = 2.200</math>  <math>Q \text{ кг.} = 0.596</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 140.2</math>  <math>P \text{ вн.мм} = 172.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-65</b></p> <p> <math>F \text{ см}^2 = 13.962</math>  <math>Q \text{ кг.} = 3.784</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 233.9</math>  <math>P \text{ вн.мм} = 172.8</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-70</b></p> <p> <math>F \text{ см}^2 = 2.492</math>  <math>Q \text{ кг.} = 0.675</math>  <math>D \text{ оп.мм} = 94.0</math>  <math>P \text{ н.мм} = 223.0</math>  <math>P \text{ вн.мм} = 190.0</math>  Гр. сл. = V  Точн. = П </p>























	<p><b>ПЗ-71</b></p> <p> <math>F \text{ см}^2 = 1.711</math>  <math>Q \text{ кг.} = 0.464</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 256.0</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-76</b></p> <p> <math>F \text{ см}^2 = 6.455</math>  <math>Q \text{ кг.} = 1.749</math>  <math>D \text{ оп.мм} = 61.6</math>  <math>P \text{ н.мм} = 175.0</math>  <math>P \text{ вн.мм} = 147.6</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-72</b></p> <p> <math>F \text{ см}^2 = 2.587</math>  <math>Q \text{ кг.} = 0.701</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} = 129.6</math>  <math>P \text{ вн.мм} = 34.6</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-77</b></p> <p> <math>F \text{ см}^2 = 9.677</math>  <math>Q \text{ кг.} = 2.622</math>  <math>D \text{ оп.мм} = 129.3</math>  <math>P \text{ н.мм} = 429.3</math>  <math>P \text{ вн.мм} = 294.4</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-73</b></p> <p> <math>F \text{ см}^2 = 2.740</math>  <math>Q \text{ кг.} = 0.743</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} = 133.3</math>  <math>P \text{ вн.мм} = 34.6</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-78</b></p> <p> <math>F \text{ см}^2 = 3.734</math>  <math>Q \text{ кг.} = 1.012</math>  <math>D \text{ оп.мм} = 85.0</math>  <math>P \text{ н.мм} = 461.6</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
			<p><b>ПЗ-79</b></p> <p> <math>F \text{ см}^2 = 8.222</math>  <math>Q \text{ кг.} = 2.228</math>  <math>D \text{ оп.мм} = 111.6</math>  <math>P \text{ н.мм} = 472.8</math>  <math>P \text{ вн.мм} = 233.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-75</b></p> <p> <math>F \text{ см}^2 = 14.285</math>  <math>Q \text{ кг.} = 3.871</math>  <math>D \text{ оп.мм} = 149.1</math>  <math>P \text{ н.мм} = 371.0</math>  <math>P \text{ вн.мм} = 341.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-80</b></p> <p> <math>F \text{ см}^2 = 11.447</math>  <math>Q \text{ кг.} = 3.102</math>  <math>D \text{ оп.мм} = 159.8</math>  <math>P \text{ н.мм} = 572.8</math>  <math>P \text{ вн.мм} = 331.0</math>  Гр. сл. = V  Точн. = П </p>











	<p><b>ПЗ-81</b></p> <p> <math>F \text{ см}^2 = 13.330</math>  <math>Q \text{ кг.} = 3.612</math>  <math>D \text{ оп.мм} = 184.2</math>  <math>P \text{ н.мм} = 622.8</math>  <math>P \text{ вн.мм} = 378.5</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-86</b></p> <p> <math>F \text{ см}^2 = 2.663</math>  <math>Q \text{ кг.} = 0.722</math>  <math>D \text{ оп.мм} = 56.1</math>  <math>P \text{ н.мм} = 189.1</math>  <math>P \text{ вн.мм} = 123.6</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-82</b></p> <p> <math>F \text{ см}^2 = 8.445</math>  <math>Q \text{ кг.} = 2.289</math>  <math>D \text{ оп.мм} = 81.6</math>  <math>P \text{ н.мм} = 225.0</math>  <math>P \text{ вн.мм} = 195.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-87</b></p> <p> <math>F \text{ см}^2 = 2.809</math>  <math>Q \text{ кг.} = 0.761</math>  <math>D \text{ оп.мм} = 58.5</math>  <math>P \text{ н.мм} = 198.1</math>  <math>P \text{ вн.мм} = 132.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-83</b></p> <p> <math>F \text{ см}^2 = 10.445</math>  <math>Q \text{ кг.} = 2.831</math>  <math>D \text{ оп.мм} = 103.8</math>  <math>P \text{ н.мм} = 275.0</math>  <math>P \text{ вн.мм} = 245.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-88</b></p> <p> <math>F \text{ см}^2 = 6.285</math>  <math>Q \text{ кг.} = 1.703</math>  <math>D \text{ оп.мм} = 60.1</math>  <math>P \text{ н.мм} = 171.0</math>  <math>P \text{ вн.мм} = 141.6</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-84</b></p> <p> <math>F \text{ см}^2 = 12.365</math>  <math>Q \text{ кг.} = 3.351</math>  <math>D \text{ оп.мм} = 126.2</math>  <math>P \text{ н.мм} = 323.0</math>  <math>P \text{ вн.мм} = 293.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-89</b></p> <p> <math>F \text{ см}^2 = 2.690</math>  <math>Q \text{ кг.} = 0.729</math>  <math>D \text{ оп.мм} = 56.0</math>  <math>P \text{ н.мм} = 253.0</math>  <math>P \text{ вн.мм} = 147.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-85</b></p> <p> <math>F \text{ см}^2 = 1.381</math>  <math>Q \text{ кг.} = 0.374</math>  <math>D \text{ оп.мм} = 36.8</math>  <math>P \text{ н.мм} = 128.9</math>  <math>P \text{ вн.мм} = 59.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-90</b></p> <p> <math>F \text{ см}^2 = 1.974</math>  <math>Q \text{ кг.} = 0.535</math>  <math>D \text{ оп.мм} = 46.9</math>  <math>P \text{ н.мм} = 152.6</math>  <math>P \text{ вн.мм} = 88.4</math>  Гр. сл. = V  Точн. = П </p>











	<p><b>ПЗ-91</b></p> <p> <math>F \text{ см}^2 = 2.044</math>  <math>Q \text{ кг.} = 0.554</math>  <math>D \text{ оп.мм} = 46.9</math>  <math>P \text{ н.мм} = 158.0</math>  <math>P \text{ вн.мм} = 93.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-96</b></p> <p> <math>F \text{ см}^2 = 2.050</math>  <math>Q \text{ кг.} = 0.556</math>  <math>D \text{ оп.мм} = 37.0</math>  <math>P \text{ н.мм} = 109.9</math>  <math>P \text{ вн.мм} = 99.1</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-92</b></p> <p> <math>F \text{ см}^2 = 3.432</math>  <math>Q \text{ кг.} = 0.930</math>  <math>D \text{ оп.мм} = 52.8</math>  <math>P \text{ н.мм} = 236.8</math>  <math>P \text{ вн.мм} = 93.4</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-97</b></p> <p> <math>F \text{ см}^2 = 23.600</math>  <math>Q \text{ кг.} = 6.396</math>  <math>D \text{ оп.мм} = 187.0</math>  <math>P \text{ н.мм} = 504.0</math>  <math>P \text{ вн.мм} = 566.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-93</b></p> <p> <math>F \text{ см}^2 = 2.537</math>  <math>Q \text{ кг.} = 0.688</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 113.1</math>  <math>P \text{ вн.мм} = 110.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-98</b></p> <p> <math>F \text{ см}^2 = 17.600</math>  <math>Q \text{ кг.} = 4.770</math>  <math>D \text{ оп.мм} = 130.0</math>  <math>P \text{ н.мм} = 384.0</math>  <math>P \text{ вн.мм} = 446.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-94</b></p> <p> <math>F \text{ см}^2 = 5.387</math>  <math>Q \text{ кг.} = 1.460</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 345.7</math>  <math>P \text{ вн.мм} = 180.3</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-99</b></p> <p> <math>F \text{ см}^2 = 1.340</math>  <math>Q \text{ кг.} = 0.363</math>  <math>D \text{ оп.мм} = 27.0</math>  <math>P \text{ н.мм} = 98.0</math>  <math>P \text{ вн.мм} = 36.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-95</b></p> <p> <math>F \text{ см}^2 = 0.324</math>  <math>Q \text{ кг.} = 0.088</math>  <math>D \text{ оп.мм} = 8.0</math>  <math>P \text{ н.мм} = 25.1</math>  <math>P \text{ вн.мм} = 38.8</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-100</b></p> <p> <math>F \text{ см}^2 = 1.760</math>  <math>Q \text{ кг.} = 0.477</math>  <math>D \text{ оп.мм} = 37.0</math>  <math>P \text{ н.мм} = 126.0</math>  <math>P \text{ вн.мм} = 36.0</math>  Гр. сл. = V  Точн. = П </p>

	<p><b>ПЗ-101</b></p> <p> <math>F \text{ см}^2 = 8.588</math>  <math>Q \text{ кг.} = 2.327</math>  <math>D \text{ оп.мм} = 127.0</math>  <math>P \text{ н.мм} = 319.7</math>  <math>P \text{ вн.мм} = 323.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-106</b></p> <p> <math>F \text{ см}^2 = 4.963</math>  <math>Q \text{ кг.} = 1.345</math>  <math>D \text{ оп.мм} = 73.0</math>  <math>P \text{ н.мм} = 181.3</math>  <math>P \text{ вн.мм} = 207.3</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-102</b></p> <p> <math>F \text{ см}^2 = 7.339</math>  <math>Q \text{ кг.} = 1.989</math>  <math>D \text{ оп.мм} = 127.0</math>  <math>P \text{ н.мм} = 307.8</math>  <math>P \text{ вн.мм} = 344.7</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-107</b></p> <p> <math>F \text{ см}^2 = 8.719</math>  <math>Q \text{ кг.} = 2.363</math>  <math>D \text{ оп.мм} = 160.0</math>  <math>P \text{ н.мм} = 365.5</math>  <math>P \text{ вн.мм} = 304.7</math>  Гр. сл. = 0соб.  Точн. = Н </p>
	<p><b>ПЗ-103</b></p> <p> <math>F \text{ см}^2 = 1.421</math>  <math>Q \text{ кг.} = 0.385</math>  <math>D \text{ оп.мм} = 35.4</math>  <math>P \text{ н.мм} = 158.5</math>  <math>P \text{ вн.мм} = 68.9</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-108</b></p> <p> <math>F \text{ см}^2 = 3.384</math>  <math>Q \text{ кг.} = 0.917</math>  <math>D \text{ оп.мм} = 53.0</math>  <math>P \text{ н.мм} = 169.3</math>  <math>P \text{ вн.мм} = 156.1</math>  Гр. сл. = 0соб.  Точн. = Н </p>
	<p><b>ПЗ-104</b></p> <p> <math>F \text{ см}^2 = 1.609</math>  <math>Q \text{ кг.} = 0.436</math>  <math>D \text{ оп.мм} = 42.8</math>  <math>P \text{ н.мм} = 188.8</math>  <math>P \text{ вн.мм} = 70.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-109</b></p> <p> <math>F \text{ см}^2 = 7.001</math>  <math>Q \text{ кг.} = 1.897</math>  <math>D \text{ оп.мм} = 126.2</math>  <math>P \text{ н.мм} = 502.6</math>  <math>P \text{ вн.мм} = 26.3</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-105</b></p> <p> <math>F \text{ см}^2 = 2.327</math>  <math>Q \text{ кг.} = 0.631</math>  <math>D \text{ оп.мм} = 41.0</math>  <math>P \text{ н.мм} = 193.9</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-110</b></p> <p> <math>F \text{ см}^2 = 1.389</math>  <math>Q \text{ кг.} = 0.376</math>  <math>D \text{ оп.мм} = 33.0</math>  <math>P \text{ н.мм} = 121.4</math>  <math>P \text{ вн.мм} = 85.3</math>  Гр. сл. = 0соб.  Точн. = П </p>











	<p><b>ПЗ-111</b></p> <p> <math>F \text{ см}^2 = 4.961</math>  <math>Q \text{ кг.} = 1.344</math>  <math>D \text{ оп.мм} = 93.0</math>  <math>P \text{ н.мм} = 266.6</math>  <math>P \text{ вн.мм} = 166.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-116</b></p> <p> <math>F \text{ см}^2 = 2.962</math>  <math>Q \text{ кг.} = 0.803</math>  <math>D \text{ оп.мм} = 43.4</math>  <math>P \text{ н.мм} = 143.0</math>  <math>P \text{ вн.мм} = 120.4</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-112</b></p> <p> <math>F \text{ см}^2 = 37.692</math>  <math>Q \text{ кг.} = 10.215</math>  <math>D \text{ оп.мм} = 160.0</math>  <math>P \text{ н.мм} = 418.6</math>  <math>P \text{ вн.мм} = 340.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-117</b></p> <p> <math>F \text{ см}^2 = 1.196</math>  <math>Q \text{ кг.} = 0.324</math>  <math>D \text{ оп.мм} = 27.7</math>  <math>P \text{ н.мм} = 94.0</math>  <math>P \text{ вн.мм} = 26.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-113</b></p> <p> <math>F \text{ см}^2 = 2.444</math>  <math>Q \text{ кг.} = 0.662</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 91.0</math>  <math>P \text{ вн.мм} = 18.9</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-118</b></p> <p> <math>F \text{ см}^2 = 4.000</math>  <math>Q \text{ кг.} = 1.084</math>  <math>D \text{ оп.мм} = 75.8</math>  <math>P \text{ н.мм} = 277.5</math>  <math>P \text{ вн.мм} = 152.1</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-114</b></p> <p> <math>F \text{ см}^2 = 5.728</math>  <math>Q \text{ кг.} = 1.552</math>  <math>D \text{ оп.мм} = 74.0</math>  <math>P \text{ н.мм} = 263.5</math>  <math>P \text{ вн.мм} = 18.9</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-119</b></p> <p> <math>F \text{ см}^2 = 5.109</math>  <math>Q \text{ кг.} = 1.385</math>  <math>D \text{ оп.мм} = 128.4</math>  <math>P \text{ н.мм} = 348.1</math>  <math>P \text{ вн.мм} = 211.9</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-115</b></p> <p> <math>F \text{ см}^2 = 4.036</math>  <math>Q \text{ кг.} = 1.094</math>  <math>D \text{ оп.мм} = 82.0</math>  <math>P \text{ н.мм} = 272.8</math>  <math>P \text{ вн.мм} = 193.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-120</b></p> <p> <math>F \text{ см}^2 = 6.406</math>  <math>Q \text{ кг.} = 1.736</math>  <math>D \text{ оп.мм} = 111.1</math>  <math>P \text{ н.мм} = 367.6</math>  <math>P \text{ вн.мм} = 303.9</math>  Гр. сл. = V  Точн. = П </p>








	<p><b>ПЗ-121</b></p> <p> <math>F \text{ см}^2 = 2.841</math>  <math>Q \text{ кг.} = 0.770</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>R \text{ н.мм} = 215.6</math>  <math>R \text{ вн.мм} = 93.9</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-126</b></p> <p> <math>F \text{ см}^2 = 2.384</math>  <math>Q \text{ кг.} = 0.646</math>  <math>D \text{ оп.мм} = 55.7</math>  <math>R \text{ н.мм} = 168.8</math>  <math>R \text{ вн.мм} = 89.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-122</b></p> <p> <math>F \text{ см}^2 = 2.504</math>  <math>Q \text{ кг.} = 0.679</math>  <math>D \text{ оп.мм} = 74.1</math>  <math>R \text{ н.мм} = 258.3</math>  <math>R \text{ вн.мм} = 48.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-127</b></p> <p> <math>F \text{ см}^2 = 2.028</math>  <math>Q \text{ кг.} = 0.550</math>  <math>D \text{ оп.мм} = 53.0</math>  <math>R \text{ н.мм} = 196.1</math>  <math>R \text{ вн.мм} = 48.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-123</b></p> <p> <math>F \text{ см}^2 = 4.500</math>  <math>Q \text{ кг.} = 1.220</math>  <math>D \text{ оп.мм} = 46.2</math>  <math>R \text{ н.мм} = 96.8</math>  <math>R \text{ вн.мм} = 28.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-128</b></p> <p> <math>F \text{ см}^2 = 1.839</math>  <math>Q \text{ кг.} = 0.498</math>  <math>D \text{ оп.мм} = 46.4</math>  <math>R \text{ н.мм} = 163.2</math>  <math>R \text{ вн.мм} = 57.3</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-124</b></p> <p> <math>F \text{ см}^2 = 3.278</math>  <math>Q \text{ кг.} = 0.888</math>  <math>D \text{ оп.мм} = 90.1</math>  <math>R \text{ н.мм} = 276.0</math>  <math>R \text{ вн.мм} = 101.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-129</b></p> <p> <math>F \text{ см}^2 = 3.235</math>  <math>Q \text{ кг.} = 0.877</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>R \text{ н.мм} = 253.5</math>  <math>R \text{ вн.мм} = 117.6</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-125</b></p> <p> <math>F \text{ см}^2 = 3.644</math>  <math>Q \text{ кг.} = 0.988</math>  <math>D \text{ оп.мм} = 32.0</math>  <math>R \text{ н.мм} = 232.6</math>  <math>R \text{ вн.мм} = 146.5</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-130</b></p> <p> <math>F \text{ см}^2 = 2.720</math>  <math>Q \text{ кг.} = 0.737</math>  <math>D \text{ оп.мм} = 47.0</math>  <math>R \text{ н.мм} = 208.0</math>  <math>R \text{ вн.мм} = 95.6</math>  Гр. сл. = IV  Точн. = П </p>

	<p><b>ПЗ-131</b></p> <p> <math>F \text{ см}^2 = 1.799</math>  <math>Q \text{ кг.} = 0.488</math>  <math>D \text{ оп.мм} = 31.0</math>  <math>P \text{ н.мм} = 148.0</math>  <math>P \text{ вн.мм} = 47.4</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-136</b></p> <p> <math>F \text{ см}^2 = 9.680</math>  <math>Q \text{ кг.} = 2.623</math>  <math>D \text{ оп.мм} = 111.0</math>  <math>P \text{ н.мм} = 369.0</math>  <math>P \text{ вн.мм} = 84.0</math>  Гр. сл. = V  Точн. = Н </p>
	<p><b>ПЗ-132</b></p> <p> <math>F \text{ см}^2 = 1.868</math>  <math>Q \text{ кг.} = 0.506</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 96.0</math>  <math>P \text{ вн.мм} = 43.5</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-137</b></p> <p> <math>F \text{ см}^2 = 1.857</math>  <math>Q \text{ кг.} = 0.503</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 177.3</math>  <math>P \text{ вн.мм} = 50.2</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-133</b></p> <p> <math>F \text{ см}^2 = 8.234</math>  <math>Q \text{ кг.} = 2.231</math>  <math>D \text{ оп.мм} = 43.4</math>  <math>P \text{ н.мм} = 213.9</math>  <math>P \text{ вн.мм} = 81.8</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-138</b></p> <p> <math>F \text{ см}^2 = 0.346</math>  <math>Q \text{ кг.} = 0.094</math>  <math>D \text{ оп.мм} = 12.0</math>  <math>P \text{ н.мм} = 37.7</math>  <math>P \text{ вн.мм} = 31.4</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-134</b></p> <p> <math>F \text{ см}^2 = 3.840</math>  <math>Q \text{ кг.} = 1.041</math>  <math>D \text{ оп.мм} = 84.5</math>  <math>P \text{ н.мм} = 503.3</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-139</b></p> <p> <math>F \text{ см}^2 = 12.166</math>  <math>Q \text{ кг.} = 3.297</math>  <math>D \text{ оп.мм} = 98.0</math>  <math>P \text{ н.мм} = 311.7</math>  <math>P \text{ вн.мм} = 277.6</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-135</b></p> <p> <math>F \text{ см}^2 = 16.300</math>  <math>Q \text{ кг.} = 4.417</math>  <math>D \text{ оп.мм} = 125.0</math>  <math>P \text{ н.мм} = 452.6</math>  <math>P \text{ вн.мм} = 157.4</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>ПЗ-140</b></p> <p> <math>F \text{ см}^2 = 3.792</math>  <math>Q \text{ кг.} = 1.028</math>  <math>D \text{ оп.мм} = 97.0</math>  <math>P \text{ н.мм} = 379.0</math>  <math>P \text{ вн.мм} = 175.5</math>  Гр. сл. = VI  Точн. = П </p>

	<p><b>ПЗ-141</b></p> <p> <math>F \text{ см}^2 = 2.700</math>  <math>Q \text{ кг.} = 0.732</math>  <math>D \text{ оп.мм} = 57.0</math>  <math>P \text{ н.мм} = 219.0</math>  <math>P \text{ вн.мм} = 134.7</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>ПЗ-146</b></p> <p> <math>F \text{ см}^2 = 3.563</math>  <math>Q \text{ кг.} = 0.966</math>  <math>D \text{ оп.мм} = 56.9</math>  <math>P \text{ н.мм} = 247.4</math>  <math>P \text{ вн.мм} = 125.1</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-142</b></p> <p> <math>F \text{ см}^2 = 1.576</math>  <math>Q \text{ кг.} = 0.427</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 146.6</math>  <math>P \text{ вн.мм} = 36.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-147</b></p> <p> <math>F \text{ см}^2 = 4.068</math>  <math>Q \text{ кг.} = 1.102</math>  <math>D \text{ оп.мм} = 37.0</math>  <math>P \text{ н.мм} = 95.4</math>  <math>P \text{ вн.мм} = 34.0</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>ПЗ-143</b></p> <p> <math>F \text{ см}^2 = 2.164</math>  <math>Q \text{ кг.} = 0.586</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>P \text{ н.мм} = 182.0</math>  <math>P \text{ вн.мм} = 68.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>ПЗ-148</b></p> <p> <math>F \text{ см}^2 = 1.965</math>  <math>Q \text{ кг.} = 0.533</math>  <math>D \text{ оп.мм} = 38.5</math>  <math>P \text{ н.мм} = 146.4</math>  <math>P \text{ вн.мм} = 40.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>ПЗ-144</b></p> <p> <math>F \text{ см}^2 = 2.755</math>  <math>Q \text{ кг.} = 0.747</math>  <math>D \text{ оп.мм} = 28.1</math>  <math>P \text{ н.мм} = 216.4</math>  <math>P \text{ вн.мм} = 142.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-149</b></p> <p> <math>F \text{ см}^2 = 3.799</math>  <math>Q \text{ кг.} = 1.030</math>  <math>D \text{ оп.мм} = 72.0</math>  <math>P \text{ н.мм} = 282.7</math>  <math>P \text{ вн.мм} = 104.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-145</b></p> <p> <math>F \text{ см}^2 = 5.088</math>  <math>Q \text{ кг.} = 1.379</math>  <math>D \text{ оп.мм} = 90.1</math>  <math>P \text{ н.мм} = 360.3</math>  <math>P \text{ вн.мм} = 180.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-150</b></p> <p> <math>F \text{ см}^2 = 1.055</math>  <math>Q \text{ кг.} = 0.286</math>  <math>D \text{ оп.мм} = 25.9</math>  <math>P \text{ н.мм} = 95.0</math>  <math>P \text{ вн.мм} = 45.8</math>  Гр. сл. = IV  Точн. = П </p>



	<p><b>ПЗ-151</b></p> <p> <math>F \text{ см}^2 = 2.401</math>  <math>Q \text{ кг.} = 0.651</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 196.7</math>  <math>P \text{ вн.мм} = 93.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-156</b></p> <p> <math>F \text{ см}^2 = 2.860</math>  <math>Q \text{ кг.} = 0.775</math>  <math>D \text{ оп.мм} = 77.5</math>  <math>P \text{ н.мм} = 231.0</math>  <math>P \text{ вн.мм} = 89.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-152</b></p> <p> <math>F \text{ см}^2 = 3.158</math>  <math>Q \text{ кг.} = 0.856</math>  <math>D \text{ оп.мм} = 90.1</math>  <math>P \text{ н.мм} = 290.3</math>  <math>P \text{ вн.мм} = 79.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-157</b></p> <p> <math>F \text{ см}^2 = 2.110</math>  <math>Q \text{ кг.} = 0.572</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 179.3</math>  <math>P \text{ вн.мм} = 87.3</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-153</b></p> <p> <math>F \text{ см}^2 = 6.698</math>  <math>Q \text{ кг.} = 1.815</math>  <math>D \text{ оп.мм} = 105.2</math>  <math>P \text{ н.мм} = 430.3</math>  <math>P \text{ вн.мм} = 249.1</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-158</b></p> <p> <math>F \text{ см}^2 = 2.471</math>  <math>Q \text{ кг.} = 0.670</math>  <math>D \text{ оп.мм} = 43.1</math>  <math>P \text{ н.мм} = 273.4</math>  <math>P \text{ вн.мм} = 69.8</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-154</b></p> <p> <math>F \text{ см}^2 = 2.603</math>  <math>Q \text{ кг.} = 0.705</math>  <math>D \text{ оп.мм} = 54.9</math>  <math>P \text{ н.мм} = 204.9</math>  <math>P \text{ вн.мм} = 105.4</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-159</b></p> <p> <math>F \text{ см}^2 = 1.541</math>  <math>Q \text{ кг.} = 0.418</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 178.4</math>  <math>P \text{ вн.мм} = 75.5</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>ПЗ-155</b></p> <p> <math>F \text{ см}^2 = 2.802</math>  <math>Q \text{ кг.} = 0.759</math>  <math>D \text{ оп.мм} = 68.8</math>  <math>P \text{ н.мм} = 213.8</math>  <math>P \text{ вн.мм} = 101.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-160</b></p> <p> <math>F \text{ см}^2 = 2.010</math>  <math>Q \text{ кг.} = 0.545</math>  <math>D \text{ оп.мм} = 48.0</math>  <math>P \text{ н.мм} = 163.7</math>  <math>P \text{ вн.мм} = 178.5</math>  Гр. сл. = 0соб.  Точн. = П </p>

	<p><b>ПЗ-161</b></p> <p> <math>F \text{ см}^2 = 1.543</math>  <math>Q \text{ кг.} = 0.418</math>  <math>D \text{ оп.мм} = 41.0</math>  <math>P \text{ н.мм} = 149.4</math>  <math>P \text{ вн.мм} = 87.2</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>ПЗ-166</b></p> <p> <math>F \text{ см}^2 = 1.589</math>  <math>Q \text{ кг.} = 0.431</math>  <math>D \text{ оп.мм} = 34.4</math>  <math>P \text{ н.мм} = 138.0</math>  <math>P \text{ вн.мм} = 61.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-162</b></p> <p> <math>F \text{ см}^2 = 2.106</math>  <math>Q \text{ кг.} = 0.571</math>  <math>D \text{ оп.мм} = 44.0</math>  <math>P \text{ н.мм} = 197.0</math>  <math>P \text{ вн.мм} = 68.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>ПЗ-167</b></p> <p> <math>F \text{ см}^2 = 1.988</math>  <math>Q \text{ кг.} = 0.539</math>  <math>D \text{ оп.мм} = 41.0</math>  <math>P \text{ н.мм} = 180.0</math>  <math>P \text{ вн.мм} = 68.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>ПЗ-163</b></p> <p> <math>F \text{ см}^2 = 1.572</math>  <math>Q \text{ кг.} = 0.426</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 144.0</math>  <math>P \text{ вн.мм} = 59.0</math>  Гр. сл. = V  Точн. = П </p>		
	<p><b>ПЗ-164</b></p> <p> <math>F \text{ см}^2 = 2.343</math>  <math>Q \text{ кг.} = 0.635</math>  <math>D \text{ оп.мм} = 52.6</math>  <math>P \text{ н.мм} = 189.0</math>  <math>P \text{ вн.мм} = 106.0</math>  Гр. сл. = V  Точн. = П </p>		
	<p><b>ПЗ-165</b></p> <p> <math>F \text{ см}^2 = 2.151</math>  <math>Q \text{ кг.} = 0.583</math>  <math>D \text{ оп.мм} = 50.7</math>  <math>P \text{ н.мм} = 180.0</math>  <math>P \text{ вн.мм} = 95.0</math>  Гр. сл. = V  Точн. = П </p>		